CHANGE ZONES ABANDON\*

(other) Run & Cement

## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Liner

|  | SF 079042   |  |  |
|--|---|--|--|
|  | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME                    |  |  |
|  | 7. UNIT AGREEMENT NAME NEBU Agreemen<br>No. 1, Sec. 929 |  |  |
| 8. FARM OR LEASE NAME Northeast Blanco Unit  |   |  |  |
|  | 9. WELL NO.<br>27                                       |  |  |
| 10. FIELD OR WILDCAT NAME Blanco Mesaverde  11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA |   |  |  |
|  |   |  |  |
|  | 12. COUNTY OR PARISH 13. STATE                          |  |  |
|  | Rio Arriba NM   |  |  |
|  | 14. API NO.   |  |  |
|  | 30-039-07897  |  |  |
|  | 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6136' DF          |  |  |

5. LEASE

SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) gas ХX other well well 2. NAME OF OPERATOR Blackwood & Nichols Co., Ltd. 3. ADDRESS OF OPERATOR P. O. Box 1237, Durango, CO 81301 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 800' F/NL - 880' F/EL AT TOP PROD. INTERVAL: Same AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE (NOTE: Report results of multiple completion or zone REPAIR WELL change on Form 9-330.) PULL OR ALTER CASING MULTIPLE COMPLETE

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

7-6-83 Found 5 1/2" casing out of slip at Bradenhead. Reset 5 1/2" casing in slip. Tested 5 1/2" casing to 2200 PSI, held ok. Pressured up to 700 PSI between 5 1/2" and 7 5/8" casing, held ok.

7-10-83 Drilled new 4 3/4" hole; 5390'-5700'. Ran 18 jts. 4" - 10.46# J-55 thread FL-4S liner set at 5676'. Top of liner at 5040'. Cemented with 58 cu. ft. 50-50 Pozmix, 2% gel, 1/4# flocele/cu. ft., .6% of 1% Halad 9 and .6 of 1% CFR-2. Circulated out 5 bbls. cement and chemical wash.

| Subsurface Safety Valve: Manu. an                          | nd Type                  | Set @                           | Ft.  |  |
|--|--------------------------|---------------------------------|------|--|
| 18., I hereby certify that the forego                      | ping is true and correct |                                 |      |  |
| 31014  | TITLE District Mar       | nager date <u>July 26, 1983</u> |      |  |
| DeLasso Loos  (This space for Federal or State office use) |                          |                                 |      |  |
| APPROVED BY  |                          | DATE                            |      |  |
| CONDITIONS OF APPROVAL, IF ANY:                            |                          | AMERICO FOR REC                 | CORD |  |

\*See Instructions on Reverse Side

JUL 28 1983



