

DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☐ Fee ☒  
5. State Oil & Gas Lease No.

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Southland Royalty Company		8. Farm or Lease Name Simms Federal
3. Address of Operator P.O. Drawer 570, Farmington, NM 87499		9. Well No. #3
6. Location of Well UNIT LETTER <u>E</u> <u>1540'</u> FEET FROM THE <u>North</u> LINE AND <u>1100</u> FEET FROM THE <u>West</u> LINE, SECTION <u>11</u> TOWNSHIP <u>30N</u> RANGE <u>4W</u> NMPM.		10. Field and Pool, or Wildcat Blanco Pictured Cliffs
15. Elevation (Show whether DF, RT, GR, etc.) 6853' GL		12. County Rio Arriba

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>		COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <u>Perforation &amp; Stimulation</u> <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-8-82 Perforated the Pictured Cliffs at 3654', 3660', 3666', 3672', 3678', 3684', 3690', 3696', 3702', 3708', 3713', 3718', 3724', 3729', 3882', 3894', 3912'. Total of 17 holes. Frac'd with 134,960 gallons of fresh water & 120,000# 20/40 sand. ATP 2650 psi, AIR 32 BPM, ISIP 1000 psi. Ran 117 joints (3964.16') of 1-1/2" 2.9#, J55, EUE tubing landed at 3874.45'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Signed Sherry Sherkey TITLE Secretary DATE November 9, 1982

Original Signed by Frank T. Chavez SUPERVISOR DISTRICT # 3 DATE NOV 12 1982

CONDITIONS OF APPROVAL, IF ANY: