

ILLEGIBLE

Form 10-10-10
1-10-10

URGENT IN TRANSMISSION

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form 10-10-10
1-10-10

Lead Office **Denver, Co.**

Case No. **20000**

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERNATE CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REGRINDING OR REPAIR
NOTICE OF INTENTION TO SHUT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, BUT LEAVE OTHER (X) MARKS

April 10

10 53

WELL NO.

1-3 is located 1000 ft. from line and 1000 ft. from line of sec. 10

NE 1/4 Sec. 10

20 A.

3 A.

NE 1/4 Sec. 10

WILLIAM

WILLIAM

WILLIAM

The elevation of the derrick floor above sea level is

DETAILS OF WORK

State names of and expected depths to objective sands; show also, weights, and lengths of proposed strings; indicate casing jobs, cementing points, and all other important proposed work.

To plug from top to bottom with cement (approximately 1000 csm), set regulation
mud, fill collar & pits, level and clean up location.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced

Company **Phillips Petroleum Company**

Address **214 Patterson Building**

Denver, Colorado

By

Title

Val R. Russo
Geologist