



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No. **NM-014387**

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 13

1960

H. J. Lee Federal "B"
Well No. **2** is located **1,850** ft. from **N** line and **2,310** ft. from **E** line of sec. **23****NE 1/4** of Sec. **23** **29-N** **12-W** **NMPM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)**Wildcat**
(Field)**San Juan**
(County or Subdivision)**New Mexico**
(State or Territory)The elevation of the derrick floor above sea level is **5,668** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 6:30 P.M., April 9, 1960.

Drilled 17-1/2" hole to 289' and cemented 277' of 13-3/8" OD casing at 289' with 300 sacks of cement. Cement circulated. Tested casing with 800# pressure for 30 minutes. Tested OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **TEXACO Inc.**Address **Box 817****Farmington, New Mexico**

By

*C. H. McLeod*Title **Asst. Dist. Supt.**