



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office \_\_\_\_\_

Lease No. **SF-080721-A**

Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY  
WASHINGTON, D. C.

**Zachary Federal**

**2/20/60**

, 19\_\_

Well No. **1** is located **1090** ft. from **N** line and **890** ft. from **W** line of sec. **34**

**1/4 Sec. 34 T29N R10W** (Range) (Meridian)

**Undesignated** (Field) **San Juan** (County or Subdivision) **N.M.** (State or Territory)

The elevation of the derrick floor above sea level is **5707.1** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded well 1/2/60  
Ran and cemented 10-3/4" cas 32.75# 289' x 302' KB  
Cemented w/300 sz Reg 2 1/2 CC pipe  
Plug down 9:30 P.M. 1/3/60  
1/4/60 Tested 800# pressure 30 min Tested OK



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **SOUTHWEST PRODUCTION COMPANY**

Address **c/o Oil Reports Box 763**  
**Rebo, N. M.**

By *[Signature]*  
Agent

Title \_\_\_\_\_

