1	Ora (F	n 9	81 1961))
	_		-	



(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land	Offic	 . l	iante	Ze	
Louis	No.		9790	65	
Umit	1	he	and		

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.	SUBSEQUENT REPORT OF WATER SHUT-OFF.
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Ragood		Movember	. 19.60
	located 1790 ft. from	N line and 1830 ft. fro	m W line of sec.
Section 34 (% Sec. and Sec. No.)	7-29H B. (Rwp.) (Re	nge) (Meridian)	
Total Gallup (Field)	Sen Juan (County or Su	pdivision)	Mexico (State or Territory)

The elevation of the derrick floor above sea level is ... 5791. ft. 6.1.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and langths of proposed casings; indicate mudding jobs, comessing points, and all other important proposed work)

P.B.T.D. - 5626'
Sand-Oil freced with 24,000# sand and 570 Bbls. Oil
Breakdown pr. 1750
Max. 2100#
Avg. treating pr. 2000#
5- min. shut-in - 900#
1.R. 35.9 bpm
Ban 182 jts, 5595' of 2 3/8" tubing, landed at 5604'
Flowing through tubing.



I understand that this plan of work must receive approval in writing	by the Geological Survey before operations may be commenced.
Company Astec Otl and Gas Company	
Address Dresser # 570	
Farmington, New Mexico	By Joe C. Belmon
······································	Title District Superintendent