

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. ST 078931-B
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 7, 1961

USA Glenn H. Callow "B"
Well No. 4 is located 810 ft. from N line and 890 ft. from Ex line of sec. 31
NW/4 Sec. 31 29 N 13 W N.M.P.M.
($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Cha Cha Gallup San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)


The elevation of the ground level above sea level is 5857 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run and cement surface casing as follows:

Ran 4 joints (130') 8-5/8", 24#, J-55, suls, casing and set at 144'. Cemented with 100 sacks regular cement. Circulated cement to surface. Plug down 9:45 a.m. 11-6-61. WOC 12 hours. Pressure tested casing to 600 pounds for 30 minutes. Pressure held o.k.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Tenneco Corp., acting by and thru its managing agent, Tenneco Oil Co.

Address P. O. Box 1714

Durango, Colorado

By L. B. Plumb

Title District Production Superintendent