

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF-080781

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Cain

9. WELL NO.

#3

10. FIELD AND POOL, OR WILDCAT

Blanco Mesaverde

11. SEC., T., R., M., OR BLE. AND
SURVEY OR AREA

Section 30, T29N, R9W

12. COUNTY OR PARISH

13. STATE

San Juan

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER
2. NAME OF OPERATOR
Southland Royalty Company
3. ADDRESS OF OPERATOR
P.O. Drawer 570, Farmington, New Mexico
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

990' ENL & 2310' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, CR, etc.)

5664' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11-16-77 MIRU. Blew well. Spotted 60 sacks at 4300'. Pulled 70 joints of 2-3/8" EU 8Rd. Shut well in.

11-17-77 Shot 4 holes in casing at 2195'. Spotted 115 sacks (75 sxs outside 4-1/2" and 40 sxs inside). Spotted 20 sacks at 1100'. Spotted 10 sacks at 235'. Spotted 10 sacks plug at surface. Pulled 143 joints of 2-3/8", 4.7#, EUE, 8 Rd tubing.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

District Production Manager

DATE

1-13-78

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

COMMITTEE OF APPROVAL IF ANY:

JUN 23 1978

*See Instructions on Reverse Side

P. T. McGRATH

DISTRICT ENGINEER