


**Limits and Closure:**

The scope of services consisted of the performance of a site assessment, soil sampling, field screening of soil, laboratory analysis of soil, excavation of soil, backfilling of the excavation, arrangement for transport and disposal of excavated soils, and preparation of a summary report. All work has been performed in accordance with generally accepted hazardous materials management professional practices.


This document has been prepared by **On Site Technologies Limited Partnership** for the exclusive use of the Mr. Orville Slaughter, as it pertains to the referenced location. If there are any questions regarding this report, please contact either Cindy Gray or Larry Trujillo at (505) 325-5667.

Respectfully,

Reviewed by;



Lawrence Trujillo, CHMM # 9461  
Senior Environmental Technician



Cynthia Sluyter-Gray, CHMM # 8695  
Environmental Project Manager

**On Site Technologies Limited Partnership**

Enclosures:

Test Hole Location Map  
Tank Relocation Map  
Sample Location Map  
Photos  
Tail Gate Safety Meeting Forms  
Laboratory Results, QA/QC, Chain of Custody

CC:

NMOCD, Denny Foust, 1000 Rio Brazos Road, Aztec, NM 87401 (2 Copies)  
Trujillo Signature File  
Sluyter-Gray Signature File  
Job File