

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____

Navajo

Allottee _____

Lease No. 11-20-603-2172

X	25		

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Casing Report

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 19, 1961

Navajo Tribe of Indians #1

Well No. 14 is located 2070 ft. from N line and 680 ft. from W line of sec. 25

SW 1/4 Section 25

29N

11W

12PM

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Cha Cha Gallup

San Juan

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 5515' Ungraded ground.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

*pudded 6-4-61.

Set 7 joints, 219', 8-5/8" OD casing at 232', and cemented to surface with 130 sacks.

Set 170 joints, 5393', 4-1/2" OD casing at 5380', and cemented with 150 sacks.



I understand that this plan of work must receive approval in writing by the Geological Survey before it can be commenced.

Company Humble Oil & Refining Company

Address P. O. Box 3082,

Durango, Colorado

COPY (ORIGINAL SIGNED) B. M. BRADLEY

By B. M. Bradley

Title Dist. Supt.