

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SP 079069
Unit Magrod

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 11, 1961


Magrod
Well No. 6-6 is located 300 ft. from N line and 2110 ft. from E line of sec. 29
NE 1/4 Section 29 T-63N R-13W S. 21, T. 21,
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Total 3-114p San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5700 ft. G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded 1/3/61
Set 10 jcs., 315' of 8 3/8" casing, landed at 325' with 225 sacks cement
Tested casing with 300# pressure for 30 minutes. It leaks.
Drilled cement plug 1/4/61
Tested with 300# pressure for 30 minutes.,
No drop in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Amoco Oil and Gas Company

Address Box # 570

Farlington, New Mexico

By NORMAN C. JOE ORIGINAL SIGNED BY JOE C. SALMON
Joe C. Salmon

Title District Superintendent