

TABULATION OF DEVIATION TESTS
PAN AMERICAN PETROLEUM CORPORATION
GALLEGOS CANYON UNIT - DAKOTA NO. 151

<u>DEPTH</u>	<u>DEVIATION</u>
359'	1/4°
569'	1/4°
945'	1/2°
1345'	1/2°
1748'	1/2°
2148'	3/4°
2503'	3/4°
2832'	1°
3163'	1°
3555'	1°
3766'	1°
4144'	1°
4546'	1°
5004'	3/4°
5423'	3/4°
5608'	1°
6071'	1°
6280'	3/4°

A F F I D A V I T

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation tests taken on PAN AMERICAN PETROLEUM CORPORATION'S Gallegos Canyon Unit - Dakota Well No. 151, Basin Dakota Field, located in the SW/4 of NE/4 of Section 21, T-29-N, R-12-W, San Juan County, New Mexico.

Signed

F. H. Hollingsworth
Petroleum Engineer

THE STATE OF NEW MEXICO)
COUNTY OF SAN JUAN) SS.

BEFORE ME, the undersigned authority, on this day personally appeared F. H. Hollingsworth known to me to be Petroleum Engineer for Pan American Petroleum Corporation and to be the person whose name is subscribed to the above statement, who, being by me duly sworn on oath, states that he has knowledge of the facts stated herein and that said statement is true and correct.

SUBSCRIBED AND SWORN TO before me, a Notary Public in and for said County and State this 9th day of April, 1964.

S. K. Hunt
Notary Public

