

Land Office 070266
Lease No. San Jacinto
Unit _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

December 17

Well No. 2 is located 990 ft. from N line and 950 ft. from E line of sec. 20 NE Sec. 20

ASTORIA, O. (Twp.) East (Range) (Meridian) New Mexico

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

12-12-57 Total depth 2055'. C.O.T.D. 2018. Water fractured Pictured Cliffs perf. int. 1934-1976 w/39,000 gallons water and 40,000% sand. BD pr. 2000#, max. pr. 2900#, avg. tr. pr. 1650, 2800, 2500#. IR 51 B/M. Flush 3150 gallons. Dropped 1 set of 20 balls for 2 stages. Mixed 1% calcium chloride with frac. water.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Box 997

Address Farmington, New Mexico

Original Signed D. C. Johnson

By Petroleum Engineer

Title _____