

OK

RECEIVED
JUL - 9 1999
OIL CON. DIV.
DIST. 3

District I _____

P.O. Box 1980, Hobbs, NM

District II _____

P.O. Drawer, Artesia, NM 88211

District III _____

1000 Rio Brazos Rd. Aztec, NM 87410

State Of New Mexico

Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO

APPROPRIATE

DISTRICT OFFICE

AND 1 COPY TO

SANTA FE OFFICE

(Revised 3/9/94)

PIT REMEDIATION AND CLOSURE REPORT

Operator: Conoco Inc.

Telephone: 505-324-5813

Address: 3315 Bloomfield Hwy - Farmington, NM 87401

Facility Or: Maxey #1

Well Name _____

Location: Unit or Qtr/Qtr Sec B Sec 24 T 29N R 12W County San Juan

Pit Type: Separator _____ Dehydrator _____ Other TDP

Land Type: BLM _____ State X Fee _____ Other _____

Pit Location: Pit dimension: length 14' width 14' depth 2'
(Attach diagram)

Reference: wellhead X other _____

Footage from reference: 178'

Direction from reference: 50 Degrees X East of X North
West _____ South _____

Depth To Ground Water: (Vertical distance from contaminants to seasonal high water elevation of ground water)	Less than 50 feet (20 points)	
	50 feet to 9 feet (10 points)	
	Greater than 100 feet (0 points)	
	Total	<u>0</u>
Wellhead Protection Area: (Less than 200 feet from a private domestic water source, or; less than 1000 feet from all other water sources)	Yes (20 points)	
	No (0 points)	
	Total	<u>0</u>
Distance To Surface Water: (Horizontal distance to perennial lakes, ponds, rivers, streams, creeks, irrigation canals and ditches)	Less than 200 feet (20 points)	(20 points)
	200 feet to 1000 feet (10 points)	(10 points)
	Greater than 1000 feet (0 points)	(0 points)
	Total	<u>0</u>
	RANKING SCORE (TOTAL POINTS):	<u>0</u>


Date Remediation Started:			Date Completed:	
Remediation Method: (Check all appropriate sections)	Excavation:		Approx. cubic yards	
	Landfarm		Insitu Bioremediation	
	Other			
Remediation Location: (ie. landfarmed onsite, name and location of offsite facility)	Onsite		Offsite	
General Description Of Remedial Action:				
One sample was taken at 3' below bottom of pit center. No PID reading was conducted on location. Sample				
was transported to laboratory for TPH analysis per EPA Method 8015.				
OVM sample = 2 ppm				
Ground Water Encountered:	No	☒	Yes	Depth
Final Pit:	Sample location		Center of pit below bottom of pit	
Closure Sampling:				
(if multiple samples attach sample results and diagram of sample locations and depths)	Sample depth		3'	
	Sample date		2/2/99 Sample time 1041	
Sample Results				
	Benzene (ppm)		n/a	
	Total BTEX (ppm)		n/a	
	Field headspace (ppm)		2	
	TPH		ND	
Ground Water Sample:	Yes	☐	No	☒ (If yes, attach sample results)
I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF				
DATE	6-28-99		PRINTED NAME	
SIGNATURE	J. L. Valley		AND TITLE P.L.	

Lease Name: Maxey 1 Operator: S H Miller Date: 9/2/98

Site Security

(Indicate North)

to P-3 gathering system



Lease Name: Maxey 1

Federal/ Indian Lease No: NM 013885

CA No.: 8910073590

Unit : B

Legal Description: Sec: 24 T: 29N R: 12W

County: San Juan, NM

Load line valves :
Sealed during Production

Drain line valves :
Sealed during Production

Production Line valve:
Sealed during sales

This lease is subject to the site security plan for
San Juan Basin Operations. The plan is located at:
Conoco Inc.
3315 Bloomfield Hwy
Farmington, NM



MAXEY 1

Date Feb. 2, 1999


TANK Drip TANK

Rocky AND Sandy Soil - Lots of Rock.


North Sample
Time: 10:48 1 PPM

West Sample
Time: 10:56
1 PPM

EAST Sample
Time: 10:51
2



South Sample
Time: 11:03
1 PPM



Date: 2-2-99

TECHNOLOGIES, LTD.

Distribution:	White – On Site	Yellow – LAB	Pink – Sampler	Goldenrod – Client
---------------	-----------------	--------------	----------------	--------------------



657 W. Maple • P.O. Box 2606 • Farmington NM 87499
LAB: (505) 325-5667 • FAX: (505) 325-6256

Purchase Order No.:		Job No.	
Name Shirley Ebert		Title	
Company CONOCO INC.		Company	
Address 3315 Bloomfield Hwy		Mailing Address	
City, State, Zip FARMINGTON, N.M. 87401		City, State, Zip	
Telephone No.		Telefax No.	

Sampling Location: MAXEY 1 TANK DRIP PIT			
Sampler: Judson Valdez			

SAMPLE IDENTIFICATION	SAMPLE		MATRIX	PRES.	Number of Containers	REPORT RESULTS TO	Name	Title
	DATE	TIME						
Center of Pit.	2-2-99	10:41	SOIL	None	2	BTX 8015 TPH 8020		
West Wall	2-2-99	10:56	SOIL	None	1			
East Wall	2-2-99	10:51	SOIL	None	2			
North Wall	2-2-99	10:48	SOIL	None	1			
South Wall	2-2-99	11:03	SOIL	None	1			
APR Composite	2/2/99		Soil	None	2	BTX 8015 TPH 8020		

Relinquished by: Judson Valdez		Date/Time: 2/2/99 1347		Received by:		Date/Time	
Relinquished by:		Date/Time		Received by:		Date/Time	
Relinquished by:		Date/Time		Received by:		Date/Time	
Method of Shipment:				Rush		10 Working Days	
Authorized by:				Special Instructions:			

Distribution:	White – On Site	Yellow – LAB	Pink – Sampler	Goldenrod – Client
---------------	-----------------	--------------	----------------	--------------------

OFF: (505) 325-5667



LAB: (505) 325-1556

February 24, 1999

Shirley Ebert
Conoco, Inc.
3315 Bloomfield Hwy
Farmington, NM 87401
TEL: (505) 327-9557
FAX (505) 324-5825

RE: Maxey 1 Tank Drip Pit

Order No.: 9902014

Dear Shirley Ebert,

On Site Technologies, LTD. received 2 samples on 2/2/99 for the analyses presented in the following report.

The Samples were analyzed for the following tests:

Diesel Range Organics (SW8015)
Gasoline Range Organics (SW8015)

There were no problems with the analyses and all data for associated QC met EPA or laboratory specifications except where noted in the Case Narrative.

If you have any questions regarding these tests results, please feel free to call.

Sincerely,

A handwritten signature in black ink, appearing to read "D Cox", is written over a horizontal line.

David Cox

OFF: (505) 325-5667



LAB: (505) 325-1556

On Site Technologies, LTD.

Date: 24-Feb-99

CLIENT: Conoco, Inc.
Project: Maxey 1 Tank Drip Pit
Lab Order: 9902014

CASE NARRATIVE

Samples were analyzed using the methods outlined in the following references:

Test Methods for Evaluating Solid Waste, Physical/Chemical Methods, SW846, 3rd Edition

All method blanks, laboratory spikes, and/or matrix spikes met quality assurance objectives.

OFF: (505) 325-5667



LAB: (505) 325-1556

ANALYTICAL REPORT

Date: 24-Feb-99

Client:	Conoco, Inc.	Client Sample Info:	Maxey 1 Tank Drip Pit
Work Order:	9902014	Client Sample ID:	Center of Pit
Lab ID:	9902014-01A	Matrix:	SOIL
Project:	Maxey 1 Tank Drip Pit	Collection Date:	2/2/99 10:23:00 AM
		COC Record:	5665

Parameter	Result	PQL	Qual	Units	DF	Date Analyzed
DIESEL RANGE ORGANICS		SW8015				Analyst: DC
T/R Hydrocarbons: C10-C28	ND	25		mg/Kg	1	2/22/99
GASOLINE RANGE ORGANICS		SW8015				Analyst: HR
T/R Hydrocarbons: C6-C10	ND	0.18		mg/Kg	1	2/6/99

Qualifiers:

PQL - Practical Quantitation Limit
ND - Not Detected at Practical Quantitation Limit
J - Analyte detected below Practical Quantitation Limit
B - Analyte detected in the associated Method Blank

S - Spike Recovery outside accepted recovery limits
R - RPD outside accepted recovery limits
E - Value above quantitation range
Surr: - Surrogate

1 of 1

P.O. BOX 2606 • FARMINGTON, NM 87499

- TOWARD A CLEANER BUSINESS - INDUSTRY WITH THE ENVIRONMENT -

OFF: (505) 325-5667



LAB: (505) 325-1556

ANALYTICAL REPORT

Date: 24-Feb-99

Client:	Conoco, Inc.	Client Sample Info:	Maxey 1 Tank Drip Pit
Work Order:	9902014	Client Sample ID:	4pt Wall Comp
Lab ID:	9902014-02A	Matrix:	SOIL
Project:	Maxey 1 Tank Drip Pit	Collection Date:	2/2/99 10:49:00 AM
		COC Record:	5665

Parameter	Result	PQL	Qual	Units	DF	Date Analyzed
DIESEL RANGE ORGANICS		SW8015				Analyst: DC
T/R Hydrocarbons: C10-C28	ND	25		mg/Kg	1	2/23/99
GASOLINE RANGE ORGANICS		SW8015				Analyst: HR
T/R Hydrocarbons: C6-C10	ND	0.18		mg/Kg	1	2/6/99

Qualifiers:

PQL - Practical Quantitation Limit
ND - Not Detected at Practical Quantitation Limit
J - Analyte detected below Practical Quantitation Limit
B - Analyte detected in the associated Method Blank

S - Spike Recovery outside accepted recovery limits
R - RPD outside accepted recovery limits
E - Value above quantitation range
Surr: - Surrogate

1 of 1

P.O. BOX 2606 • FARMINGTON, NM 87499

TECHNOLOGY BEING BUILT TO LIVE WITH THE ENVIRONMENT