

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different interval. Use Form 9-231-C for such proposals.)

1. ☒ OK well ☒ OK ☐ other Depleted

2. NAME OF OPERATOR
Texas Eastern Developments, Inc.

3. ADDRESS OF OPERATOR
P.O. Box 2521 Houston, Texas 77001

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 2321 FSL 1682 FEL
AT TOP PROD. INTERVAL
AT TOTAL DEPTH:

26. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.
REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:
TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
PULL OR ALTER CASING
MULTIPLE COMPLETE
CHANGE ZONES
ABANDON - ~~Temporary~~ ☒ P&A
(other)

SUBSEQUENT REPORT OF:

RECEIVED

JAN 16 1987

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

RECEIVED

JAN 26 1987

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

27. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)⁶

Well numerations in accordance with survey by San Juan Engineering Company, Inc. of December 1980 (was Shiprock 17J1).

WELL DATE

WELL DATE
Spud 3/24/61 TD 84' Hole Size 6 3/4" Csg 5 1/2" @ 67.7 cmt'd w/ 5" sx.

METHOD OF PLUGGING

REMOVE TUBING, RODS & PUMP.

Squeeze Gallup Sand (69' - 78') w/ 10 sx neat cmt, fill 5 1/2" csg w/cmt to surface, set marker.

Subsurface Safety Valve: Manu. and Type _____

22. I hereby certify that the foregoing is true and correct

SIGNED H. N. Hinds TITLE Dir. Supt. DATE 1/1/50

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL IF ANY. 011 00 1587

Other Instructions on Reverse Side

NMOCG

APPROVED

JAN 28 1987

John Skellie

AREA MANAGER
FARMINGTON RESOURCE AREA