State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

| | Sundry Notices and Reports | |
|---|--|----------------------------------|
| | | API # (assigned by OCD) |
| | | 30-045-08388 |
| Type of Well | | 5. Lease Number |
| GAS | | 6. State Oil&Gas Lease ‡ |
| | | |
| | | E-3146-2 7. Lease Name/Unit Name |
| Name of Operator | | 7. Lease Name/Unit Name |
| BURLINGTON | | |
| | GAS COMPANY | Schultz Com D |
| | | 8. Well No. |
| Address & Phone No. of Operato | or | #8 |
| PO Box 4289, Farmington, NM 87499 (505) 326-9700 | | 9. Pool Name or Wildcat |
| | | Aztec Pictured Cliff |
| Location of Well, Footage, Sec | ., T, R, M | 10. Elevation: |
| 990'FNL, 1190'FEL, Sec.16, T- | 29-N, R-10-W, NMPM, San Juan | County, NM |
| Type of Submission | Type of Action | of Plans |
| X Notice of Intent | Abandonment Char | age of Plans |
| | Abandonment Char Recompletion New | Construction Proving Exacturing |
| Subsequent Report | _ Plugging Back Non- | er Shut off |
| | Casing Repair Wate | romaion to Injection |
| | altering Casing CON | Version to injection |
| Final Abandonment | Alcering easing | |
| 3. Describe Proposed or Compl It is intended to repair t | X_ Other - Tubing Repair | |
| 3. Describe Proposed or Compl | _X_ Other - Tubing Repair eted Operations | |