



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office San Antonio
Lease No. 17-776973
Unit None

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 10, 1959

Well No. 2 is located 290 ft. from N line and 290 ft. from E line of sec. 15

T-290 1-10 T-290
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
As 000 San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5726 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth - 2178' 1925' - 2125' perforated from 2121 to 2137, 2138-2142, with 2 shots per foot and from 2123 to 2115 with 1 shot per foot. Sand-water free with 60,000' sand and 44,070 gals. water. Breakdown pressure - 500#, Maximum pressure 1000#, Minimum pressure 300# - 1. 1. 10 bpm. Final pressure 500#. Landed 57 lbs. (2125') of 1" dg. at 2122'. Shut in for pump.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ALCOA CO. INC. COMPANY
Address Box 776
Marathon, New Mexico
By Joe C. Salas
Title District Superintendent