

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Santa Fe**
Lease No. **078110**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

JAN 17 1962

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

N. M. Federal "I" _____ **January 16**, 1962

Well No. **5** is located **330** ft. from **N** line and **2510** ft. from **E** line of sec. **14**

NE 1/4 NW 1/4 Sec. 14

(1/4 Sec. and Sec. No.)

29N

(Twp.)

14W

(Range)

NWPM

(Meridian)

Totah Gallup

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the ~~surface~~ **ground** above sea level is **5440** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD 5282'. We have plugged and abandoned this well.

Set cement plugs as follows:


5050'-5200'

3750'-3850'

950'-1050'

350'-450'

Installed 4" X 6' marker on top of hole and clean location.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Sunray Mid-Continent Oil Company**

Address **200 Pet. Club Plaza Building**

Farmington, New Mexico

ORIGINAL SIGNED BY

E. H. RAINLEY

By _____

Title **District Manager**