

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. <b>SF 065557</b>
2. NAME OF OPERATOR <b>PRODUCING ROYALTIES INC.</b>	6. IF INDIAN, ALLOTTEE OR TRIBE NAME <b>30-045-08425</b>
3. ADDRESS OF OPERATOR <b>P.O. Box 1071, LUBBOCK, TEXAS 79408</b>	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface <b>1090' fsl &amp; 990' fcl Sec. 11, T29N, R12W, SAN JUAN Co. New Mexico</b>	8. FARM OR LEASE NAME <b>CORNELLY</b>
14. PERMIT NO.	9. WELL NO. <b>12</b>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <b>5718</b>	10. FIELD AND POOL, OR WILDCAT <b>FULCHER KUTZ PC</b>
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <b>Sec. 11, T29N, R12W NMPM</b>
	12. COUNTY OR PARISH <b>SAN JUAN</b>
	13. STATE <b>NM</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

**THIS WELL HAS BEEN PLUGGED AND ABANDONED AS FOLLOWS:**

**JUNE 7, 1979** Move in Rig. Spot 40% cement plug 1899' to 1700'

**JUNE 8, 1979** Set Hydraulic jacks work 7" casing.

**JUNE 12, 1979** Shot 7" casing off at 625', Pull 7" casing.

Go in hole with tubing, Spot 60% plug from 700' to 550'. Pull tubing.

**JUNE 13, 1979** Set P&A marker with 10% surface plug.  
Clean location.

18. I hereby certify that the foregoing is true and correct

SIGNED **Larry G. Bedford**

TITLE **AGENT For Operator**

DATE **Aug 10, 1982**

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED  
AS AMENDED

Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

1WR 1-21-85 BC

See Instructions on Reverse Side

FARMINGTON COPY

JAN 14 1985  
**John Miller**  
MILLERBACH  
AREA MANAGER

See

SF-065557 (WC)  
3162.3-4 (016)

Caller Service 4104  
Farmington, New Mexico 87499

*Bla*  
*ats*

JUL 31 1986

Producing Royalties, Inc.  
P.O. Box 1071  
Lubbock, TX 79408

Gentlemen:

Your well No. 12 Cornell located 1090' FSL and 990' FEL, sec. 11, T. 29 N.,  
R. 12 W., lease No. SF-065557 was inspected on July 25, 1986, and found  
ready for abandonment. Therefore, the well is hereby approved for final  
abandonment.

Sincerely,

(SGD.) STEVE HENKE

FOR

John S. McKee  
Acting Area Manager

cc:

Well file  
Suspense (BamEnde)

016:BamEnde; cab: 7/28/86