UNITED STATES DEPARTMENT OF THE INTERIOR

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF-076958 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
reservoir, Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas K other	Hare
2. NAME OF OPERATOR	9. WELL NO. #14:
Southland Royalty Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Blanco Mesa Verde/Basin Dakota
P. O. Drawer 570, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec. 10, T29N, R10W
AT SURFACE: 1450' FSL & 1850' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan NM
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	5. ALEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner 1-26-81 1. MIRU. 2. Pulled tubing, replaced bad joints, install 3. Installed new seal assembly in packer at 66 4. Rigged down. 5. Return well to production.	e all pertinent details, and give pertinent dates, irectionally drilled, give subsurface locations and it to this work.)*
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct SIGNED TITLE DISTRICT Engi	neer DATE AGGERTED FOR RECORD
(This space for Federal or State off	1.1AR & 1301
APPROVED BY TITLE TOTAL CONDITIONS OF APPROVAL, IF ANY:	FARMINGTON DISTRICT