

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 52 065551
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 20, 1955

Well No. 7 is located 1190 ft. from N line and 1820 ft. from W line of sec. 10

10/4 (1/4 Sec. and Sec. No.) 20-N (Twp.) 12-W (Range) N.M.P.M. (Meridian)
Kuts (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK


(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pictured Cliffs sand at approximately 1950 feet

8-5/8", 24 pound, approximately 95 feet with 75 sacks of cement.

5-1/2", 14 pound, approximately 1950 feet with 100 sacks of cement.

well is to be fraced with approximately 20,000 gals. of water and approximately 20,000 pounds of sand.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Red M. White
Address 740 Casino Real
El Paso, Texas

By H. L. Lanning
Title Agent

Company.....MC MILLAN AND WHITE.....

Lease.....Well No.....7.....


Sec. 10....., T. 29 N....., R. 12 W., N.M.P.M.....

Location.....1190' FROM THE NORTH LINE AND 1840' FROM
THE WEST LINE.....

Elevation.....5675.7 UNGRADED GROUND.....

SAN JUAN COUNTY

NEW MEXICO



Scale—4 inches equal 1 mile.

This is to certify that the above plat was prepared from field notes of actual surveys made by me or under my supervision and that the same are true and correct to the best of my knowledge and belief.

Seal:

James P. Leese
Registered Land Surveyor.
James P. Leese
N. Mex. Reg. No. 1463

Surveyed 29 October, 19 55

SAN JUAN ENGINEERING COMPANY, FARMINGTON, N. M.

