

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 52-06517
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 28, 1955

Well No. 6 is located 790 ft. from N line and 1830 ft. from E line of sec. 11

1/4 Sec. and Sec. No.)

29 (Range)

12 (Range)

1 (Range)

29 (Field)

San Juan (County or Subdivision)

New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pictured Cliffs sand at approximately 1950 feet

3-5/8", 24 pound, approximately 95 feet with 75 sacks of cement

5-1/2", 14 pound, approximately 1950 feet with 100 sacks of cement

Well is to be fraced with approximately 20,000 gals of water and approximately 20,000 pounds of sand.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Red W. White

Address 740 Camino Real

El Paso, Texas

By H. L. Lamm

Title Agent

