

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division


Sundry Notices and Reports on Wells

<p>1. Type of Well GAS</p> <hr/> <p>2. Name of Operator <b>BURLINGTON RESOURCES</b> OIL &amp; GAS COMPANY</p> <hr/> <p>3. Address &amp; Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700</p> <hr/> <p>4. Location of Well, Footage, Sec., T, R, M <i>R</i> 1180' FSL, 1030' FEL Sec. 2, T-29-N, R-11-W, NMPM, San Juan County</p>	<p>API # (assigned by OCD) 300450866200</p> <p>5. Lease Number</p> <p>6. State Oil&amp;Gas Lease # E-3521</p> <p>7. Lease Name/Unit Name  MIMS COM</p> <p>8. Well No. 1</p> <p>9. Pool Name or Wildcat Aztec PC</p> <p>10. Elevation: 5,804' GL</p>
-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Type of Submission	Type of Action	
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other - Restimulation	

13. Describe Proposed or Completed Operations

Pull 1 1/4" tubing.  
Clean out to PBTD @ 2,155'.  
Acidize and foam fracture treat PC zone.  
Clean out well.  
Run tubing.  
Return well to production.



SIGNATURE

Regulatory Administrator December 3, 1999

(This space for State Use)

OFFICIAL NOTICE OF COMPLAINT

OFFICIAL NOTICE OF COMPLAINT

DEC 7 1999

Approved by

Title

Date

# MIMS COM #1

Section 2 A, T-29-N R-11-W  
San Juan, New Mexico

## Aztec PC Field Wellbore Schematic

