

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allettee 1-69-IND-56
Lease No. _____

| | | |
|--|----------|--|
| | | |
| | X | |
| | | |

Section 2

SUNDRY NOTICES AND REPORTS ON WELLS

| | | |
|---|--|----------|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF | |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING | |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING | |
| NOTICE OF INTENTION TO REDRILL OR REPAIR WELL | SUBSEQUENT REPORT OF REDRILLING OR REPAIR | |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT | X |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY | |
| NOTICE OF INTENTION TO ABANDON WELL | | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 24, 1961

Well No. 137 is located 1650 ft. from N line and 1650 ft. from E line of sec. 2

NE 1/4 Sec. 2
(1/4 Sec. and Sec. No.)

T-29 N, R-19 W
(Twp.) (Range)

NMPN
(Meridian)

Rattlesnake
(Field)

San Juan County
(County or Subdivision)

New Mexico
(State or Territory)
RECEIVED
APR 26 1961
CON. COM.
3

The elevation of the derrick floor above sea level is 5269 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 12-30-60. Drilled with cable tools to 507' T. D. Ran & cemented 32' of 9 5/8" casing w/15 sks. reg. Ran 507' of 4 1/2" casing cemented w/100 sks. Perforated w/4 shots/ft. 184'-230'; 260' - 300'; & 438' - 458'. Set packer @ 380'. Sandfraced w/10,000 # sand, 500 # ADOHITE, & 242 Bbls. crude. Pulled packer. With retrievable plug @ 307' & packer @ 165', sandfraced w/12,000 # sand, 100 # ADOHITE & 350 Bbls. crude. Pulled plug & packer, ran tubing & rods, and pump tested well. Pumped 1 BO PD for 14 days, 248 Bbls of lead oil remaining to recover. Well shut in pending further study.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 3312

Durango, Colorado

Original Signed By:
H. D. HALEY

By _____

Title District Superintendent