

RANKING SCORE (TOTAL POINTS): 10

Date Remediation Started: February 7, 1995 Dated Completed: March 16, 1995

Remediation Method: Excavation Approx. cubic yards
(Check all appropriate sections) Landfarmed Insitu Bioremediation

Other Excavated 3ft below surface of pit and ran headspace test
(1.6ppm) and 418.1 (10ppm) - Repeated headspace at 5ft (1.6ppm)

Remediation Location: Onsite Offsite Test results proved that no
(ie. landfarmed onsite, name and location of offsite facility) remediation was needed.

General Description Of Remedial Action: Test results proved that no
remediation of soils would be necessary.

PID headspace test = 1.6 ppm

418.1 = 10ppm

Ground Water Encountered: No X Yes Depth

Final Pit: Sample location South West side of pit. This is
Closure Sampling: the downgradient direction
(if multiple samples, attach sample results and diagram of sample locations and depths) Sample depth 3 ft. + 5 ft.
Sample date 3/16/95 Sample time 9:30 am

Sample Results

Benzene(ppm)

Total BTEX(ppm)

Field headspace(ppm) 1.6 ppm

TPH 10ppm

Ground Water Sample: Yes No X (If yes, attach sample results)



I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE 3/16/95

SIGNATURE Randy J. Elledge

PRINTED NAME Randy J. Elledge
AND TITLE Environmental Technician

ec | Twn 29 Rng 13
 16 = A
 se No. = Fee
 anty - San Juan
 ute - N. M.



- Field Notes and Data
- Fenced perimeter (chain link)
 - Earthen pit is outside fenced area
 - Earthen pit is netted
 - 95 bbl steel tank is screened
 - size of equipment is not necessarily to scale