

STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Santa Fe
Land Office 078555-A
Lease No. _____
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 22, 1951

Well No. 1-35 is located 1090 ft. from N line and 1162 ft. from E line of sec. 18
N. E. 1/4 Sec. 18 T-30-N R-8-W NMPM
Blanco-La Plata (Twp.) San Juan (Range) (Meridian) New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6393 ft. D. F.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run 111 joints of 7" 20# J-55 casing landed at 4806' with 200 sacks of regular cement and with full returns throughout job. Casing is set in top of Cliffhouse formation; cable tools with rotary attachment using gas will be moved in for Mesa Verde completion and thru well will be shot with SHG. Water shut-off test will be made after drilling plug with cable tools.

Present T. D. 4806'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Delhi Oil Corporation


Address P. O. Box 1175

Farmington, New Mexico

By J. B. Howell
Title Superintendent

Land Office _____
 Lease No. _____
 Unit _____

(SUBMIT IN TRIPLICATE)
 UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	
NOTICE OF INTENTION TO CHANGE PLANT	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	
NOTICE OF INTENTION TO SHOOT OR ABANDON	
NOTICE OF INTENTION TO PULL OR ALTER Casing	
NOTICE OF INTENTION TO ABANDON WELL	
SUBSEQUENT REPORT OF WATER SHUT-OFF	
SUBSEQUENT REPORT OF SHOOTING OR ABANDONING	
SUBSEQUENT REPORT OF ALTERING CASING	
SUBSEQUENT REPORT OF REPAIRING OR REPAIR	
SUBSEQUENT REPORT OF ABANDONMENT	
SUPPLEMENTARY WELL HISTORICAL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OF DATA)

Well No. _____ is located _____ ft from _____ line and _____ ft from _____ line of sec. _____

(County or subdivision) _____ (State or Territory) _____

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; know slimes, weights, and levels of proposed work; include all other important proposed work)

I understand that this plan of work must receive approval in writing of the Geological Survey before operations may be commenced.

Company _____

Address _____

By _____

Time _____