

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF	<input checked="" type="checkbox"/>	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

February 11, 1953
(Date)Farmington, New Mexico
(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

El Paso Natural Gas Company
(Company or Operator)Mamos Pool Unit
(Lease)Pioneer Drilling Company
(Contractor)

Well No. 1 in the NW 1/4 SW 1/4 of Sec. 11

T. 30N, R. 8W, NMPM., Blanco Pool, San Juan County.

The Dates of this work were as follows: February 6, 1953

Notice of intention to do the work (was) (wasn't) submitted on Form C-102 on December 19, 1952,
(Cross out incorrect words)

and approval of the proposed plan (was) (wasn't) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

Total Depth 4230'.

Ran 133 joints 7", 20#, J-55 casing (4218') set at 4230' with 300 sacks regular cement and two sacks Floccals.

Top of cement at 2900' by temperature survey.

Held 1200# for 30 minutes.

Witnessed by D. E. Lockett, El Paso Natural Gas Company, Petroleum Engineer
(Name) (Company) (Title)

Approved: OIL CONSERVATION COMMISSION

Emery C. Arnold
(Name)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name: E. C. Arnold

Position: Petroleum Engineer

Representing: El Paso Natural Gas Company

Address: P.O. Box 997, Farmington, New Mexico

Checked by Inspector Dist. #3.

(Title)

2-16-53
(Date)

This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some minor discoloration and faint smudges, characteristic of old paper. The left edge of the page shows the binding structure, including what appears to be stitching or staples. The page is set against a dark background, which makes the lighter color of the paper stand out. There is no text or other markings on the page.