
DEC 8 G 1949

Meter Number: 75526
Location Name: Simmons #6 PC
Location: TN-29 RG-09
SC-24 UL-L
2 - Federal
NMOCD Zone: OUTSIDE
Hazard Ranking Score: 00



# RATIONALE FOR RISK-BASED CLOSURE OF PRODUCTION PITS LOCATED OUTSIDE OF THE VULNERABLE ZONE IN THE SAN JUAN BASIN

This production pit location was ranked according to the criteria in the New Mexico Oil Conservation Division's Unlined Surface Impoundment Closure Guidelines and received a ranking score of zero. The estimated depth to groundwater is greater than 100-feet beneath ground surface (bgs), the pit is not in a well head protection area, and there are no surface water bodies within 1,000 horizontal feet of the pit location.

The primary source, discharge to the pit has been removed. There has been no discharge to the pits for at least 4 years and the pits have been closed for at least one year.

Each pit was backfilled with clean soil and graded in a manner to divert precipitation away from the excavated area. Minimal infiltration of rainfall is expected. Any rainfall that does infiltrate the ground surface must migrate through clean backfill before reaching the residual hydrocarbons.

There is no source material at the ground surface, so direct contact of hydrocarbons with livestock and the populous is not likely.

In general, outside of the vulnerable area and alluvial valleys, bedrock material is generally encountered within 20 feet of the ground surface. Bedrock material in the San Juan Basin consists of interbedded sandstones, shales and clays. According to Freeze and Cherry, 1979, the hydraulic conductivity of the bedrock material are as follows:

Sandstone  $10^{-9}$  to  $10^{-13}$  cm/sec Shale  $10^{-12}$  to  $10^{-16}$  cm/sec Clay  $10^{-12}$  to  $10^{-15}$  cm/sec

Based on this information, the residual hydrocarbons should not migrate to groundwater.

Natural process (bioremediation) are degrading the residual hydrocarbon to carbon dioxide and water and will continue until the source is gone, therefore minimizing any impact to the environment.

Based on the above information, it is highly unlikely that any source material will impact groundwater or ever find an exposure pathway to affect human health and therefore El Paso Field Services Company (EPFS) requests closure of this pit location.




## FIELD PIT SITE ASSESSMENT FORM

GENERAL	Meter: 75526Location: Simmon's 6 PC  Operator #: 8043 Operator Name: 10.5 immons P/L District: 13.6 immons P/L District: 1
	NMOCD Zone:         Land Type:         BLM         ⋈ (1)           (From NMOCD         State         (2)           Maps)         Inside         (1)         Fee         (3)           Outside         (2)         Indian         Indian           Depth to Groundwater         (1)         (1)         (2)           Less Than 50 Feet (20 points)         (1)         (2)           Greater Than 100 Ft (0 points)         (3)         (3)
SESSMENT	Wellhead Protection Area:  Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction?, or; Is it less than 200 ft from a private domestic water source? (1) YES (20 points) (2) NO (0 points)
SITE ASS	Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points)
	(Surface Water Body: Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds)  Distance to Nearest Ephemeral Stream (1) < 100'(Navajo Pits Only)  (2) > 100'  TOTAL HAZARD RANKING SCORE: POINTS
7	Remarks: P+A Redkine + Topo both show outside VZ.
REMAR.	Wilh chose Pit
REN	Push In

### ORIGINAL PIT LOCATION

Original Pit: a) Degrees from North 353° Footage from Wellhead 129'

b) Length : <u>/3'</u> Width : <u>/5'</u> Depth : <u>2'</u>



Remarks:

Photos: 4 pict 10:40

Completed By:

Signature

6-9-95

Date

## FIEL PIT REMEDIATION/CLOSU E FORM

GENERAL	Meter: 75524 Location: 5:mmov #6 pc  Coordinates: Letter: 1 Section 24 Township: 29 Range: 09  Or Latitude Longitude  Date Started: 7-5-95 Run: 13 51
FIELD OBSERVATIONS	Sample Number(s): MK U20  Sample Depth: K' Feet  Final PID Reading 224 PID Reading Depth K' Feet  Yes No  Groundwater Encountered X Approximate Depth Feet
CLOSURE	Remediation Method:  Excavation  Onsite Bioremediation  Backfil Pit Without Excavation  Soil Disposition:  Envirotech  Other Facility  Name:  Pit Closure Date: 7-5-95  Pit Closed By: pailins
REMARKS	Remarks: Arrived took pence down Aug Sample Hole 1st  R' appeared to be also next d' Black soil and the 165t  2' appeared to also up again soil Brown strong Hydroceron  odor  Signature of Specialist: Morga Tkillian



## FIELD SERVICES LABORATORY ANALYTICAL REPORT

## PIT CLOSURE PROJECT - Soil Samples Outside the GWV Zone

#### SAMPLE IDENTIFICATION

	Fiel	d iD	Lab ID			
SAMPLE NUMBER:	MK	420	+1-195 946948 246948			
MTR CODE   SITE NAME:	7552	75526		N/A		
SAMPLE DATE   TIME (Hrs):	7-5-95		1500			
SAMPLED BY:	N/A					
ATE OF TPH EXT.   ANAL.:	7-6	<u>-95</u>	7.6.95			
ATE OF BTEX EXT.   ANAL.:						
TYPE   DESCRIPTION:	V a	<del></del>	From Flad & Clay			
PARAMETER	RESULT	UNITS	QUALIFIERS			
		Ollifo	DF	Q	M(g)	V(ml)
TPH (418.1)	2040	MG/KG			1.97	28
HEADSPACE PID	224	PPM				
	86.9	%				
PERCENT SOLIDS						
PERCENT SOLIDS		TPH is by EPA Metho	od 418.1			
PERCENT SOLIDS	<u> </u>	TPH is by EPA Metho	od 418.1			

Approved By:

95/07/06 13:38

Sample identification 746948

Initial mass of sample, g 1.970

Volume of sample after extraction, ml 18.000

Petroleum hydrocarbons, ppm 3043.807

Net absorbance of hydrocarbons (2930 cm-1) 0.254

