	DEPART	UNITED STATES MENT OF THE INTE	SUBMIT IN TRIPLICAT. (Other instructions on verse side)	re Budget Burear	No 42-1/1424	
		GEOLOGICAL SURVEY	The state of the s	5. LEASE DESIGNATION A I-89-IND-57	ND SERIAL NO.	
SU	INDRY NOT	ICES AND REPORTS	ON WELLS	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.) 1.				Navajo Tribe		
WELL WELL MAME OF OPERATOR				7. UNIT AGREEMENT NAM	-	
Eastern Petroleum Company				8. FARM OR LEASE NAME Navajo	8. FARM OR LEASE NAME Navajo	
. ADDRESS OF OPERAT		9. WELL NO.				
P. O. Box 226, Farmington, New Mexico 87401 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*				#5		
See also space 17 b At surface	elow.)		Rattlesnake-Dakota			
		i	11. SEC., T., B., M., OR BLK. AND			
2310' FNL - 990' FEL				SURVEY OR AREA		
1 0000	PERMIT NO. 15 ELPUATIONS (Short which the state of the st			Sec.2,T29N,R19W		
r. chair ao.		15. ELEVATIONS (Show whether DF, RT, GR, etc.)			12. COUNTY OR PARISH 13. STATE	
		5285 GL			New Mexic	
	Check Ap	propriate Box To Indicate	Nature of Notice, Report, or	Other Data		
	NOTICE OF INTENS		1	QUENT REPORT OF:		
TEST WATER SHUT	-OFF P	CULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WE		
FRACTURE TREAT	M	ULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CAST		
SHOOT OR ACIDIZE	Α	BANDON*	SHOOTING OR ACIDIZING	ABANDONMENT	x	
REPAIR WELL (Other)	C	HANGE PLANS	(Other)	ho - 2 144-1		
·	OP COMPLETED OPER	Diministra (CD)	Completion or Recomment details, and give pertinent dates	ts of multiple completion on pletion Report and Log form		
		gs:				
Dakota Top Plug		0 w/3sx				
Dakota Top Plug Ł Errected a	700-8 g 0-1 4'4" marke	0 w/3sx	eady for inspection.			
Dakota Top Plug Ł Errected a	700-8 g 0-1	0 w/3sx	eady for inspection.	Fig. 1 of 10		
Dakota Top Plug Ł Errected a	700-8 g 0-1 4'4" marke	0 w/3sx	eady for inspection.			
Dakota Top Plug Ł Errected a	700-8 g 0-1 4'4" marke	0 w/3sx	eady for inspection.	IAN 9 1 107		
Dakota Top Plug Ł Errected a	700-8 g 0-1 4'4" marke	0 w/3sx r and location is r red.	ED CHENTER	JAN 3 1 1973	3	
Dakota Top Plug Ł Errected a	700-8 g 0-1 4'4" marke	0 w/3sx	ED CHENTER			
Dakota Top Plug Ł Errected a	700-8 g 0-1 4'4" marke	o w/3sx r and location is r red. FEB 1 19	PATS	JAN 3 1 197; U. S. GEOLOGICAL SUIFERMINGTON, N. W.	אובע	
Dakota Top Plug Ł Errected a	700-8 g 0-1 4'4" marke	0 w/3sx r and location is r red.	273 OM.	U. S. GEOLOGICAL SUI	אובע !	
Dakota Top Plug ¿ Errected a	700-8 g 0-1 4'4" marke	o w/3sx r and location is r red. FEB 1 15 OIL CON. C	273 OM.	U. S. GEOLOGICAL SUI	אַנייי	