

ILLEGIBLE

Form 9-331
(May 1963)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM - 03561	
2. NAME OF OPERATOR Aztec Oil and Gas Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR Drawer 570, Farmington, New Mexico		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650 FSL & 1650 FWL, Sec. 5-29N-10W		8. FARM OR LEASE NAME Grenier B	
14. PERMIT NO.		9. WELL NO. 6	
15. ELEVATIONS (Show whether DE, RT, OR, etc.) 5791 Gr		10. FIELD AND POOL, OR WILDCAT Aztec, Pictured Cliffs	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 5-29N-10W	
		12. COUNTY OR PARISH San Juan	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

Spud Report

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*


10-3-68

Rigged up. TD 100'. Ran 3 jts 8-5/8" J-55 24# casing, set @ 99' cemented with 80 sx Class A, 2% CaCl. Pressure tested to 500# - held OK.

RECEIVED

OCT 2 1968

U. S. GEOLOGICAL SURVEY
FARMINGTON, N.M.



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

District Superintendent

DATE

10-17-68

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side