

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-321-C for such proposals.)

1. ☒ Oil well ☒ Gas well ☐ Other DEPLETED

2. NAME OF OPERATOR  
Texas Eastern Developments, Inc.

3. ADDRESS OF OPERATOR  
P.O. Box 2521 Houston, Texas 77001

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 2311 FNL 1368 FEL  
AT TOP PROD. INTERVAL  
AT TOTAL DEPTH:

5. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

CHANGE ZONES

ABANDON ~~Well~~

(other)

SUBSEQUENT REPORT OF:

RECEIVED

JAN 16 1987

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

RECEIVED

JAN 26 1987

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)  
Well numeration in accordance with survey by San Juan Engineering Company, Inc. of December 1980 (was Navajo 17671).

WELL DATA

Spud 8/8/69 TD 111' Hole Size 5 5/8" Csg 4 1/2" @ 111' cmt'd w/ B sx.

METHOD OF PLUGGING

REMOVE TUBING, RODS, & PUMP.

Squeeze Gallup Sand (95.5' 99.0') w/ 10 sx neat cmt, fill 4 1/2" csg w/cmt to surface, set marker.

Subsurface Safety Valve: Manu. and Type

28. I hereby certify that the foregoing is true and correct

SIGNED M. N. Hinds TITLE Drlg Supt DATE FEB 02 1987

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL IF ANY.

TITLE \_\_\_\_\_ DATE \_\_\_\_\_

MOCC FEB 04 1987

OIL CON. DIV.  
DIST. 6

See instructions on reverse side