UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

ı 9–331 . 1973	Form Approved. Budget Bureau No. 42-R1424			
UNITED STATES	5. LEASE			
DEPARTMENT OF THE INTERIOR	SF 080724 A			
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME			
not use this form for proposals to drill or to deepen or plug back to a different voir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME			
oil gas yy	Zachry			
well well well other	9. WELL NO.			
NAME OF OPERATOR	22			
Supron Energy Corporation	10. FIELD OR WILDCAT NAME			
ADDRESS OF OPERATOR	Bloomfield Chacra Extension			
P.O. Box 808, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR			
LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA			
below.) AT SURFACE: 950 Ft./N; 1520 Ft./E line	Sec. 33, T-29N, R-10W, N.M.P.M.			
	12. COUNTY OR PARISH 13. STATE			
AT TOP PROD. INTERVAL: Same as above AT TOTAL DEPTH: Same as above	San Juan New Mexico			
Dame us above	14. API NO.			
CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,				
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5659 R.K.B.			
UEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	250			
WATER SHUT-OFF				
CTURE TREAT U U				
AIR WELL	(NOTE: Report results of multiple completion or zone			
OR ALTER CASING	change on Form 9–330.)			
TIPLE COMPLETE				
nge zones 🔲 🔲				
NDON*	3 %			
er) Ran 2-7/8" E.U.E. Tubing				
DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinen	irectionally drilled, give subsurface locations and			
Drilled 6-3/4" hole with mud to total depth of total depth on 12/10/80.	of 3045 ft. R.K.B. Reached			
Ran 100 joints of 2-7/8" E.U.E., 6.50# tubing at 3042 ft. R.K.B. with float collar at 3032				
Cemented with 330 sacks of 65-35-6 with 12-1, and 200 sacks of 50-50 poz mix with 2% gel at				

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)							
1. oil		gas well	ХХ	other	-		

2. NAME OF OPERATOR Supron Energy Corporation

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON*

3. ADDRESS OF OPERATOR P.O. Box 808, Farmington, New Mexico 87401

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 1 AT SURFACE: 950 Ft./N; 1520 Ft./E line

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA

- Ran 100 joints of 2-7/8" E.U.E., 6.50# tubis at 3042 ft. R.K.B. with float collar at 303
- Cemented with 330 sacks of 65-35-6 with 12and 200 sacks of 50--50 poz mix with 2% gel sack. Plug down at 4:30 P.M. 12/10/80.
- Circulated 20 bbl. of cement slurry to the surface.

Subsurface Safety Valve: Manu. and Type $_$	Set @	Ft.		
18. I hereby certify that the foregoing is tru	e and correct			
SIGNED Dunch E. Codly Kenneth E. Roddy	TITLE Production Supt.	DATE	December 11, 1980	
Kenneth E. Roddy				
	(This space for Federal or State office use			
APPROVED BY	TITLE	DATE	<u> </u>	
CONDITIONS OF APPROYAL DE ANY				

ACCEPTED FUR RECORD

*See Instructions on Reverse Side

FARMINGTON DISTRICT

DEC 1 2 1980