UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

5.	LEASE	
SF	047020	В
6.	IF INDIAN,	ALLOTTEE OR TRIBE NAME

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME		
	Congress		
1. oil gas de	9. WELL NO.		
2. NAME OF OPERATOR	9		
SUPRON ENERGY CORPORATION	10. FIELD OR WILDCAT NAME		
3. ADDRESS OF OPERATOR	Bloomfield Chacra Ext.		
P.O. Box 808, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec. 26, T-29N, R-11W, N.M.P.M.		
AT SURFACE: 800 ft./S ; 1725 ft./W line	12. COUNTY OR PARISH 13. STATE		
AT TOP PROD. INTERVAL: Same as above	San Juan New Mexico		
AT TOTAL DEPTH: Same as above	14. API NO.		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,			
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)		
	5606 R:K, B.		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF			
REPAIR WELL	(NOTE: Report results of multiple completion or zone		
PULL OR ALTER CASING	change on form 9=3300)		
MULTIPLE COMPLETE			
CHANGE ZONES	GOOD TO THE STATE OF THE STATE		
ABANDON* (abor) Ran 2-7/8" tubing as casing string a 5			

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
 - Drilled 6-5/8" hole with mud to total depth of 2960 ft. R.K.B. Total depth was reached on 3-5-81.
 - 2. Ran 95 joints of 2-7/8" E.U.E., 6.50# tubing as casing string. Set at 2959 ft. R.K.B. with float collar at 2927 ft. R.K.B.
 - 3. Cemented with 350 sacks of 65-35-6 with 12½ lbs. of Gilsonite per sack and 200 sacks of 50-50 POZ mix with 2% gel and 10% salt. Plug down at 3:00 p.m. 3-6-81.
 - 4. Circulated 15 bbls. of cement slurry to the surface.

Subsurface Safety Valve: Manu. and Type		_	D Ft.
18. I hereby certify that the foregoing is true and correct SIGNED Structh E. Caldy TITLE Production Supt. D. Roddy	DATE	March 10,	, 1981
(This space for Federal or State office use)			
APPROVED BY TITLE TOTALL CONDITIONS OF APPROVAL, IF ANY:	DATE .		Gueriku FOR RECORI

VMOCC

MAR 12 1981