Riotra sw aut

LEASE ដី គឺ ទី១៧ SF 076958 ្ហូ ម៉ាវី

BY ___

5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas 🔀 other	Albright ខ្លួន ខ
2. NAME OF OPERATOR	9. WELL NO. 20 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
Supron Energy Corporation	8-E 영화기 등 중중단 10. FIELD OR WILDCAT NAME 표시되
3. ADDRESS OF OPERATOR	Basin Dakota: Blanco Mesawardo
P.O. Box 808, Farmington, New Mexico 87401	1. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA TO TO THE TOTAL TOTAL TO THE TOTAL
below.) AT SURFACE: 790 Ft./South; 1615 ft./East line	Sec. 15, T-29N, R-10W, N.M.P.M.
AT TOP PROD. INTERVAL: Same as above	12. COUNTY OR PARISH 13. STATE San Juan New Mexico
AT TOTAL DEPTH: Same as above	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS' (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSECUENT REPORT OF:	5691 R.K.B.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	The state of the s
FRACTURE TREAT	/FD
SHOOT OR ACIDIZE	
REPAIR WELL UP JUL 12 %	OffiOTE: Report results of multiple completion or zone change on Form 9–330.)
MULTIPLE COMPLETE TO T	
CHANGE ZONES U. S. CECLOGICAL ABANDON* FARMINGTON,	
(other) Ran 5-1/2" casing as a liner X	- TI
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinent	all pertinent details, and give pertinent dates, rectionally drilled, give subsurface locations and to this work.)*
. Drilled a 7-7/8" hole with mud to total depth	
was reached on 7/4/82.	
· Ran Dual Induction and Compensated Density Lo	
Ran 49 joints of 5-1/2", 15.50# K-55 casing a	s a liner. Bottom of the liner
was set at 6810 ft. R.K.B. Top of the liner	was set at 4/1/ ft. R.K.B.
Float collar was set at 6767 ft. R.K.B. Cemented liner with 852 cubic ft. of 50-50 Po.	mix with 2% col 10% cole
0.6% FLA, 1/4 lb. of celloflakes, and 6-1/4 l	o. of cilsonite per sack
Plug down at 9:05 A.M. 7/6/82.	
	198°
	WL I CO
	\ : " CON 3
Cubarratara Cafata Malara Marana A T	OIL DIST.
Subsurface Safety Valve: Manu. and Type	Set @Set @
18. I hereby certify that the foregoing is true and correct	The state of the s
SIGNED Synth E. Delly nile Production Supp	7/8/82
/Kenneth E. Roddy/	
(This space for Federal or State office	e use)
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:	DATE
	ACCEPTED FOR RECORD
*See Instructions on Reverse Sid	• Jul. 14 1982
	_
<u>N</u> MOCC	FARMINETON DISTRICT
	RV