MULTIPLE COMPLETE CHANGE ZONES ABANDON*

(other) Cement Bond Log - Cement

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

n 9–331 c. 1973	Form Approved. Budget Bureau No. 42-R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF 081078
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
not use this form for proposals to drill or to deepen or plug back to a different ervoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
	Albright
oil gas well other	9. WELL NO.
NAME OF OPERATOR	7 <i>-E</i>
Union Texas Petroleum Corporation	10. FIELD OR WILDCAT NAME
ADDRESS OF OPERATOR	Basin Dakota - Blanco Mesaverde
P.O. Box 808, Farmington, New Mexico 87401 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.)	Sec. 22, T29N, R10W, N.M.P.M.
AT SURFACE: 790 ft./S; 790 ft./E line	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same as above	San Juan New Mexico
AT TOTAL DEPTH: Same as above	14. API NO.
CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	5625 R.K.B.
QUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
ST WATER SHUT-OFF	Address of the Control of the Contro
OOT OR ACIDIZE	CEIVED
DAID WELL	(NOTE: Penort results of multiple completion or zone
LL OR ALTER CASING 🔲 💮 💮	P 28 1982
	1 20 1302
ANGE ZONES	- Trans Guryery
- 1 n 7 x - Compant (Ton	EGLOGICAL SURVEY MINGTON, N. M.
	Andrew Control of the
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner 	irectionally drilled, give subsurface locations and
1. <u>9-24-82</u> - MOL & RU completion rig and clea	an out to 6528'.

(Do not use this form for proposals to drill or to deepen or plug back to a different	nt
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil G gas G	Albright
1. oil gas well other	9. WELL NO.
2. NAME OF OPERATOR	7 <i>-</i> E
Union Texas Petroleum Corporation	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Basin Dakota - Blanco I
P.O. Box 808, Farmington, New Mexico 87401	11. SEC., T., R., M., OR BLK. AN
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 1 below.)	Sec. 22, T29N, R10W, N
AT SURFACE: 790 ft./S; 790 ft./E line	12. COUNTY OR PARISH 13. S
AT TOP PROD. INTERVAL: Same as above	San Juan New
AT TOTAL DEPTH: Same as above	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	=,
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, K
OURSESUE DEPORT OF	5625 R.K.B.
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT SHOOT OR ACIDIZE	ECEIVED
REPAIR WELL	(NOTE: Report results of multiple co
PULL OR ALTER CASING	CO O (Change on Form 9–330.)

9-25-82 - Blue Jet ran CBL-VDL with Collar Log from 651



Subsurface Safety Valve: Manu. and Type		Set @ Ft.
18. I hereby certify that the foregoing is t	rue and correct	
SIGNED O.B. Whitehburg	title _Area Manager	DATE September 28, 1982
	(This space for Federal or State office	use)
APPROVED BY	TITLE	DATE

LIGGEPTED FOR RECORD

*See Instructions on Reverse Side

007 1 1982

NMOCC

