

## TABULATION OF DEVIATION SURVEYS

BHP PETROLEUM (AMERICAS) INC. GALLEGOS CANYON UNIT NO. 399
API NO. 30-045-29036

Americas Division **BHP Petroleum** 

DEPTH	DEVIATION	DECTOR
152′ 646′	1/4° 3/4°	JUL 2 5 1994
1123′ 1415′	1-1/4° 1-1/2°	
		Diation Blive

**AFFIDAVIT** 

This is to certify that to the best of my knowledge the above tabulation details the deviation tests taken in the BHP PETROLEUM (AMERICAS) INC.'S Gallegos Canyon Unit No. 399 located 2196' FNL & 798' FEL of Section 24,T-29-N,R-13-W in San Juan County, New Mexico

Signed Cal Kalle

THE STATE OF TEXAS)
) SS.
COUNTY OF HARRIS

BEFORE ME, the undersigned authority, on this day personally appeared <u>Carl Kolbe</u> known to me to be <u>Regulatory Affairs</u> <u>Representative</u> for <u>BHP Petroleum (Americas) Inc.</u> and to be the person whose name is subscribed to the above statement, who, being by me duly sworn on oath, states that he has knowledge of the facts stated herein and that said statement is true and correct.

SUBSCRIBED AND SWORN TO before me, a Notary Public in and for said County and State this <u>11th</u> day of <u>July</u> 1994.



Motary Public

My Commission Expires

9/15/97

ORIGINAL