UNITED STATES

DEPARTMENT OF THE INTERIOR RECEIVED BUREAU OF LAND MANAGEMENT	
Sundry Notices and Reports on Mells 1:2	21
	<u>,</u>
H. HOTESTAN 6.70	5. Lease Number SF-065557-A
GAS	6. If Indian, All. or Tribe Name
	7. Unit Agreement Nam
Name of Operator BURLINGTON RESOURCES OIL & GAS COMPANY	
	8. Well Name & Number
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	Cornell #3R 9. API Well No. 30-045-29539
Location of Well, Footage, Sec., T, R, M	10. Field and Pool Fulcher Kutz PC
1450' FSL, 1190' FEL, Sec. 1, T-29-N, R-12-W, NMPM	11. County and State San Juan Co, NM
Subsequent Report Plugging Back Non-Rou	onstruction outine Fracturing Shut off
13. Describe Proposed or Completed Operations	
It is intended to change the surface casing program on the	
Drill an 8 %" surface hole to 120'. Run 7", 20.0# casing set from 0-120'. Cement w/46 sx Class " chloride and 0.25 pps cellophane (54 cu ft of s to circulate to surface). WOC 8 hrs. Test cas 30 minutes.	"G" w/3% calcium slurry, 200% excess
5	ECEIVED MAR 2 5 1998
14. I hereby certify that the foregoing is true and correct.	OL CON. DIV.
Signed May Makhuld Title Regulatory Administrate	DIST. 3

MMOCD

MAR 2 - 1000

(This space for Federal or State Office use)

APPROVED BY /S/ Durne W. Spencer Title

CONDITION OF APPROVAL, if any: