In Lieu of Form 3160-4 (July 1992)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUBMIT IN DUPLICATE

FORM APPROVED OMB NO. 1004-0137

(See other

Expires: February 28, 1995

instructions on LEASE DESIGNATION AND reverse side) SF-078771 LEASE NO. IF INDIAN, ALLOTTEE OR WELL COMPLETION OR RECOMPLETION REPORT AND LOG* TYPE OF WELL: OIL WELL [GAS WELL R DRY [] 7. UNIT AGREEMENT NAME ROSA UNIT (008480) OTHER Ъ. TYPE OF COMPLETION NEW WELL [WORKOVER M DEEPEN [PLUG BACK [DIFF.RESVR. [] OTHER NAME OF OPERATOR FARM OR LEASE NAME, WELL NO. DEMONSTER **ROSA UNIT #8** NORTHWEST FIPELINE CORPORATION ADDRESS AND TELEPHONE NO. APT WELL NO. 30-039-07944 P.O. BOX 58901) MS 2M3 SALT LAKE CITY, UTAH 84158-0900 (801) 584-6981 LOCATION OF WELL (seport location clearly and in accordance with any State requirements). 10. FIELD AND POOL, OR WILDCAT ROSA PICTURED CLIFFS 96175 1100' FSL & 900' FWL At Surface SEC., T.,R.,M., OR BLOCK AND SURVEY OR AREA At top production interval reported below SW/4 SW/4 SEC. 26, T31N R6W At total depth DATE ISSUED 12. COUNTY OR 13. STATE NO. **NEW MEXICO** RIO ARRIBA 16. DATE T.D REACHED DATE COMPLETED (READY TO PRODUCE) 15. DATE 18. ELEVATIONS (DK, RKB, 19. ELEVATION CASINGHEAD SPUDDED RT, GR, ETC.) * 6428 2543 00 07/02/55 08/17/55 08/01/94 20. TOTAL DEPTH, MD & TVD 5865' 21. PLUG, BACK T.D., MD & TVD 5865' 23. INTERVALS ROTARY TOOLS CABLE TOOLS MULTCOMP., HOW DRILLED BY PRODUCING INTERVAL(S), OF THIS COMPLETION - TOP, BOTTOM, NAME (MD AND TVD) PICTURED CLIFFS 3272 TO 3327 25. WAS DIRECTIONAL SURVEY MADE YES . TYPE ELECTRIC AND OTHER LOGS RUN CASED HOLE: GR/CCL/CBL PND-S 27. WAS WELL CORED 28. CASING REPORT (Report all strings set in well) WEIGHT, LB./FT. CASING DEPTH SET (MD) HOLE SIZE TOP OF CEMENT, CEMENTING RECORD AMOUNT PULLED ! ⁽¹⁾ ≟ . ∤02 SX 10-3/4" H-40 32.75# 235 13-3/4" 158 cu.ft. SURFACE 7-5/8" J-55 26.4# 3625 9-7/8" 200 SX 347 cu.ft. 2050'(CBL) 29 LINER RECORD 30. TUBING RECORD SIZE TOP (MD) BOTTOM (MD) SACKS CEMENT* SCREEN (MD) SIZE DEPTH SET (MD) PACKER SET 5-1/2" J-55 3511' 5712 100 SX (136 cu.ft.) 1-1/2" 2.9# 3324 4000 31. PERFORMATION RECORD (Interval, size, and number) 32. ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC. 3272' TO 3287', 3294' TO 3307', 3311' TO 3327' DEPTH INTERVAL (MD) AMOUNT AND KIND OF MATERIAL USED TOTAL OF 38 .36" DIA HOLES. 3272' 3327 98,300# 18,396 GAL 30# X-LINK IN 70 QUALITY FOAM 3.3 PRODUCTION DATE OF FIRST PRODUCTION WELL STATUS (PRODUCING OR SHUT IN) SHUT IN DATE OF TEST HOURS TESTED CHOKE SIZE PROD'N FOR TEST OIL - BBL. GAS - MCF WATER - BBL. GAS-OIL RATIO 08/21/94 PERIOD->>> 321 3 3/4" 0 FLOW TUBING CASING PRESSURE CALCULATED 24-HOUR RATE >>>> OIL - BBL. GAS - MCF WATER - BBL. OIL GRAVITY-791# 2,556 N/A API (CORR.) 198# 34. DISPOSITION OF GAS (Sold, used for fuel, vented, etc.) TEST WITNESSED BY CHIK CHARLEY TO BE SOLD

36. I hereby certify that $oldsymbol{g}$ ed information is complete and correct as determined from all available records

LOGS, SUMMARY OF POROUS ZONES, & WELLBORE DIAGRAM

SIGNED KATHY BARNEY


SR. OFFICE ASSISTANT DATE AUGUST 24-1994 TITLE

35. LIST OF ATTACHMENTS:

*(See Instructions and Spaces for Additional Data on Reverse Signal Title 18 U.S.C. Section 1001, makes it a crime for any person Mowingly and willfully to make to any department or agency of the United Stated any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Alic 2 & 1994 AUG 2 6 1994

WELLBORE DIAGRAM ROSA UNIT #8 PC/MV



HOLE SIZE	CASING	CEMENT	VOLUME	TOP OF CMT
13-3/4	10-3/4" 32.75#	102 SX	158 CU.FT.	SURFACE
9-7/8"	7-5/8" 26.4#	200 SX	347 CU.FT.	2050'(CBL)
6-3/4"	5-1/2" 14#	100 SX	136 CU.FT.	4626'(calc)