

STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 070094
Unit None

SUNDRY NOTICES AND REPORTS ON WELLS



NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

~~Farmington, New Mexico, November 1, 1951~~

Well No. 4 is located 1535 ft. from N line and 1775 ft. from E line of sec. 27

NE 1/4 of Section 27 1-31-N 4-4-E DEM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Section)
Wildcat Rio Arriba New Mexico
(Field) (County or Subdivision) (State & Territory)

The elevation of the derrick floor above sea level is 4895 ft. (G.L.)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was spudded at 4:00 P.M., October 12, 1951. Set 33 feet of 16" OD casing over string October 13, 1951. On October 22, 1951, 488 feet of 13-3/8" casing was set at 495 feet; 16" over string pulled. Cemented 13-3/8" casing with 200 sacks which circulated to surface 12 midnight, October 22nd. At 12 noon, October 24, 1951, hole was bailed dry and remained dry for two hours. Thirty feet of solid cement were then drilled in bottom of pipe and hole again bailed dry. Hole remained dry for two hours which was considered a satisfactory water shut-off.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Standard Oil and Gas Company

Address Box 427

Farmington, New Mexico

By D. J. Spurr

Title Production Foreman

I understand that this plan of work must receive approval in writing by the Geological Survey before it can be carried out.

Company

Address

By

Title