



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office San Antonio  
Lease No. 1-1-1787-5  
Unit 1032  
11-23-201-567

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 22, 1956

Well No. 12-15 is located 110 ft. from N line and 635 ft. from E line of sec. 15

12-15 (Twp.) 11N (Range) 1-1-1787-5 (Meridian)  
San Antonio (Field) San Antonio (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6264.4 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 2:00 p.m. 6-2-56, drilled to 200', lost 180.07' of 9-5/8" at 170.00',  
2-40, 3-40, casing 4 1/2" pattern shoe, at 176.07' and cemented 4 1/2" on reg.  
est. 1-1-56. 6-2-56. 31 hours, casing tested o.s.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San Antonio Cement & Lime Co.

Address San Antonio, Tex.

San Antonio, Tex.

By Original signed by T. A. Dugan

Title District Engineer

