UNITED STATES

UNITED STATES	5. LEASE 2024 6 202
	5. LEASE \$\frac{1}{2} \frac{1}{2} \frac{1}
DEPARTMENT OF THE INTERIOR	SF-078769
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
SUINDILL HOLICES AND INC. ONLY OF THE BACK to a different	Rosa Unit 6 - 8
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME 글 용휴명
1. oil 📆 gas 🗍	<u> </u>
well well other	9. WELL NO. 94 15 15 15 15 15 15 15 15 15 15 15 15 15
2. NAME OF OPERATOR	लें हैं हैं हैं हैं है है है है
	10. FIELD OR WILDCAT NAME
Amoco Production Company	TO. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Basin Dakota 553
501 Airport Drive Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA 호호 등 유명 등 기계
4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17	NW/4 SW/4 Section 17 T31N R5W
below.) AT SURFACE: 1850' FSL x 790' FWL Section 17,	10 COUNTY OF PARISH 12 STATE
	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: same T31N R5W	Rio Arriba S New Mexico
AT TOTAL DEPTH: same	14. API NO. 14 1 2 1 2 1 2 2 2 2 2 2 2 2 2 2 2 2 2
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. 유민경화 등 등 변경 30-039-22123 중심하다
	the state of the s
REPORT, OR OTHER DATA	13. ELEVATIONS (SHOW OF, KOB, AND WO)
	6311 写GL 显 图象显示
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	The popular control of the popular o
TEST WATER SHUT-OFF 🗌 🔲	ਹੈ ਜੋ
FRACTURE TREAT	S (a to be seen in a partie of the parties
SHOOT OR ACIDIZE	an bu bundan bunda bunda bundan bunda bundan bunda bund
REPAIR WELL	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	shapes on Form 0 220)
MULTIPLE COMPLETE	
CHANGE ZONES	(a) (b) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c
ABANDON*	Shelfochia est cago le create lo dina pendia est raibule est bulle to say bus create la cre
	ន ២៥៥៣៣ ២៥ ស្វា ១៣៣៣ ២៥ ស្វា
(other) Frac and Perf report	의 기계
Completion operations commenced on 9-24- water and pressure tested casing to 3000 pour Perforated first stage from 7998' to 801 SPF, total of 66 holes. Sand water fraced well with 152,260 gall pounds of sand. Perforated second stage from 7864' to 78 2 SPF, total of 72 holes. Sand water fraced second stage with 158, pounds sand. Flowed well back and swabbed. Released completion rig on 10-2-79. Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correct	nds, held okay. 9 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6
	5.mm
SIGNED B F TITLE Dist. Adm. S	Supr. DATE 10-3-79 STOTE 1979
(This space for Federal or State of	ffice use)
APPROVED BY CONDITIONS OF APPROVAL IF ANY: OCT 5 197 *See Instructions on Reverse DURALIZO, COLO	Side UG & SURVEY N. M.

54,M.