UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF 078999
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
SUNDRY NUTICES AND REPORTS ON WELLS	San Juan_31-6 Unit
Do not use this form for proposals to drill or to deepen or plug back to a different eservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
	San Juan 31-6 Unit
1. oil gas well other	9. WELL NO.
2. NAME OF OPERATOR	#36
Northwest Pipeline Corporation	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Basin Dakota
P.O. Box 90, Farmington, N.M. 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.)	Sec 27 T31N R6W
AT SURFACE: 845' FNL & 790' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same as above	Rio Arriba New Mexico
AT TOTAL DEPTH: Same as above	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	30-039-22488
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6132 GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)  te all pertinent details, and give pertinent dates.
including estimated date of starting any proposed work. If well is a measured and true vertical depths for all markers and zones pertine. 12-23-80 - 12-24-80  MOL & RU. Spudded 12-1/4" surface hole at 9-5/8", 36#, K-55, ST&C & set at 358' KB. w/ 1/4# gel flake/sx & 3% CaCl <sub>2</sub> . Circ out hrs 12-24-80. WOC.  12-25, 26-80 Shut down for Christmas.  12-27-80 to 12-29-80 Drlg ahead to a depth of	t 1400 hrs. Ran 9 jts (344') of Woodco cemented w/ 275 sx Cl "B" 15 bbls cmt. Plud down @ 0130
Subsurface Safety Valve: Manu. and Type  18. I hereby certify that the foregoing is true and correct  TITLE Production	Set @ Ft. Clerk DATEDec 29, 1980
(This space for Federal or State office use)	
JAN 0 8 1981  APPROVED BY	

.. . .......