

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other _____
2. NAME OF OPERATOR
Northwest Pipeline Corp
3. ADDRESS OF OPERATOR
P.O. Box 90, Farmington, N.M. 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 845' FNL & 790' FEL
AT TOP PROD. INTERVAL: Same as above
AT TOTAL DEPTH: Same as above
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- | | |
|----------------------|-------------------------------------|
| TEST WATER SHUT-OFF | <input type="checkbox"/> |
| FRACTURE TREAT | <input checked="" type="checkbox"/> |
| SHOOT OR ACIDIZE | <input type="checkbox"/> |
| REPAIR WELL | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> |
| MULTIPLE COMPLETE | <input type="checkbox"/> |
| CHANGE ZONES | <input type="checkbox"/> |
| ABANDON* | <input type="checkbox"/> |
| (other) | <input type="checkbox"/> |

SUBSEQUENT REPORT OF

REPORT OF
RECEIVED
1981

FEB 25 (NOTE:
U. S. GEOLOGICAL SURV
FARMINGTON, N. M.

rt results of a further complete on
ge on form 9-833

RECEIVED
FEB 27 1981
OIL CON.
DIST. COM.

detail and give a complete
led give surface location
*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
2-14-81 to 2-17-81 Fishing for wireline & temp tool.

2-18-81 Pressure tested csg & bridge plug to 4000# OK. Blue Jet perfed 25 holes from 7806' to 7830' @ 1 SPF. Western fraced w/ 17,400# 20/40 sand & 54,776 gal of treated wtr. Well sanded off before flush was completed. MIR 29 BPM; AIR 26 BPM; MTP 4100#; ATP 4000#. ISIP 4000# Job complete at 1145 hrs

2-19-81 Attempted to refrac.

2-20-81 Refraced w/ 40# guar gum gel. Pumped 10,000 gal pad to frac followed w/ 35,000# 20/40 sand @ 1/2 - 1 ppg. Frac job complete @ 1225 hrs 2-20-81.

2-21-81 to 2-23-81 Blowing well w/ compressor.

Subsurface Safety Valves: Manu. and Type _____ Set (1) _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Donna J. Brace TITLE Production Clerk DATE Feb 23, 1981

(This space for Federal or State office use)

APPROVED FOR RECORD
CONDITIONS OF APPROVAL, IF ANY.

FEB 26 1981

MEMO

FARMINGTON DISTRICT

*See Instructions on Reverse Side