UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE SF 078763 6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME Rosa Unit		
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME Rosa Unit		
1. OII gas well other 2. NAME OF OPERATOR	9. WELL NO. #80		
Northwest Pipeline Corporation 3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME Blanco MV & Basin Dakota		
P.O. Box 90, Farmington, N.M. 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 8 T31N R5W		
AT SURFACE: 1660' FSL & 1/80' FWL AT TOP PROD. INTERVAL: Same as above	12. COUNTY OR PARISH Rio Arriba 13. STATE New Mexico		
AT TOTAL DEPTH: Same as above 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO. (NOT RECEIVED BY NMOCC)		

REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6261' GR SUBSEQUENT REPORT OF: REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE (NOTE: Report results of multiple completion àr zone REPAIR WELL change on Form 9-330.) PULL OR ALTER CASING MULTIPLE COMPLETE : [CHANGE ZONES ABANDON* Drilling Operations (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates,

including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Dec 3, 1980 Drlg with gas.

Dec 4, 1980 Gauged well at 8015', TSTM. Ran IEL CDL/SNP/GR Logs. Ran 199 jts (8001') of 5-1/2", 17#, N80, LT&C set at 8015'. Cemented w/ 220 sx C1 "B" w/ 8% gel and 12-1/2# gil/sx & 0.4% HR-4. Tailed w/ 100 sx Cl "B" w/ l/4# tuf-plug/sx and 0.4% HR-4. Displaced plug w/ 185 bbls wtr and down at 1530 hrs. Wilson ran temp survey and found top of cement at 3100' with PBTD at 7940'. Released rig at 2000 hrs.

Dec 5, 1980 Moving rig to Rosa Unit #79. NOW WAITING ON COMPLETION RIG.

Subsurface Safety Valve: Manu. and	Туре		Set @	Ft.
18. I hereby certify that the for going signed Comma Diagram	g is true and correct	Clerk DATE	Dec 9. 1980	
Donna Brace	(This space for Federal or Sta			
APPROVED BY	TITLE	DATE		

CONDITIONS OF APPROVAL, IF ANY: