3.00

1. 44.25.64

PULL OR ALTER CASING MULTIPLE COMPLETE

CHANGE ZONES ABANDON*

Form Approved

CIL COM. COM.

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Form 9–331 Dec. 1973	Budget Bureau No. 42-R1424			
UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE SF 078773			
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME Rosa Unit			
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME Rosa Unit			
1. OII gas well other 2. NAME OF OPERATOR	9. WELL NO. #77			
Northwest Pipeline Corporation	10. FIELD OR WILDCAT NAME			
3. ADDRESS OF OPERATOR	Blanco MV & Basin Dakota			
P.O. Box 90, Farmington, N.M. 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA			
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	Sec 33 T31N R5W			
AT SURFACE: 1820' FSL & 810' FWL	12. COUNTY OR PARISH 13. STATE			
AT TOP PROD. INTERVAL: Same as above	Rio Arriba New Mexico			
AT TOTAL DEPTH: Same as above 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	14. API NO. 6351 GR			
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)			
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	2 151957 B			
TEST WATER SHUT-OFF				
REPAIR WELL	(NOTE: Report results of multiple completion or zon- change on Forth 9-3400 / 20153)			

dist. 3 Drilling (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 11/7/80 WOC Drilling ahead. Took a gas kick at 3340'. Drilling with 11/8/80 - 11/11/80

water. 11/12/80 Schlumberger ran IES/GR & CNL/FDC/GR Logs. Ran 92 jts (3756') of 7-5/8", 26.4#, K-55, LT&C & set at 3770' KB. BJ cemented with 135 sx C1 "B" 65/35 poz & 12% gel. Tailed with 75 sx Cl "B" w/ 2% CaCl.. Plug displaced with 74 bbls of water and down at 1450 hrs 11/12/80. Wilson ran temp survey and found cement top at 2650. (Ojo Alamo at 2690') with PBTD at 3725'.

11/13/80 Pick up Drill pipe.

Subsurface Safety Valve: Manu. and Type		Se	t @		.Ft.
18. I hereby certify that the foregoing is tr	ue and correct				
SIGNED DONNA Brace	TITLE Production Clerk	DATENovem	ber 13,	1980_	
ACCEPTED FOR RECURD	(This space for Federal or State office use)				
APPROVED BY CONDITION DATAPPROVIDE BY	TITLE	_ DATE			
COURTHOUGH BLALLE AND GOOD WITE	NMOCC:				

- ARMINGTON DISTRICT