

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)


1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Southland Royalty Company		8. Farm or Lease Name Chicosa Canyon
3. Address of Operator P.O. Drawer 570, Farmington, New Mexico 87401		9. Well No. 1
4. Location of Well UNIT LETTER <u>M</u> , <u>830</u> FEET FROM THE <u>South</u> LINE AND <u>1100</u> FEET FROM THE <u>West</u> LINE, SECTION <u>35</u> TOWNSHIP <u>31 North</u> RANGE <u>4 West</u> NMPM.		10. Field and Pool, or Wildcat Basin Dakota/ Wildcat Mesa Verde
15. Elevation (Show whether DF, RT, GR, etc.) 6874' GL		12. County Rio Arriba

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Spud and Casing Report</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8-11-81 Spudded 12-1/4" surface hole at 4:45 P.M. 8-10-81 and drilled to total depth of 257'. Ran 6 joints (245') of 9-5/8", 32.30#, H-40, ST&C casing set at 257'. Cemented with 130 sacks of Class "B" with 1/4# gel flake per sack and 3% CaCl₂. Plug down at 6:15 A.M. 8-11-81. Cement circulated.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Ester Greyson</u>	TITLE <u>Drilling Clerk</u>	DATE <u>August 11, 1981</u>
Original Signed by <u>FRANK T. CHAVEZ</u>		SUPERVISOR DISTRICT # <u> </u>
APPROVED BY <u> </u>	TITLE <u> </u>	DATE <u>AUG 12 1981</u>
CONDITIONS OF APPROVAL, IF ANY:		