

Rosa Unit #116  
TABULATION OF DEVIATION TESTS

AMOCO PRODUCTION COMPANY

<u>DEPTH</u>	<u>DEVIATION</u>
90'	1/4°
403'	1/4°
899'	3/4°
1492'	3/4°
1920'	3/4°
2274'	1/4°
2741'	1/4°
3274'	1/2°
3666'	1/2°
4166'	1/2°
4459'	1/2°
4957'	1/2°
5455'	1/4°
5920'	1/4°
6520'	1/4°
7020'	3/4°
7516'	1/4°
7642'	1-1/2°
7850'	3/4°

RECEIVED  
SEP 05 1984  
OIL CON. DIV  
DIST. 3

A F F I D A V I T

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation tests taken on AMOCO PRODUCTION COMPANY'S Rosa Unit #116, Sec. 24, T31N, R6W, Rio Arriba, New Mexico.

Signed

Buddy Shaw

Title Administrative Supervisor

THE STATE OF NEW MEXICO) ) SS.  
COUNTY OF SAN JUAN ) )

BEFORE ME, the undersigned authority, on this day personally appeared Buddy Shaw known to me to be Administrative for Amoco Production Company and to be the person whose name is subscribed to the above statement, who, being by me duly sworn on oath, states that he has knowledge of the facts stated herein and that said statement is true and correct.

SUBSCRIBED AND SWORN to before me, a Notary Public in and for  
said County and State this 31 day of August, 1984.

Shirley Bradshaw  
Notary Public