

OIL CONSERVATION DIVISION
NORTHWEST NEW MEXICO PACKER LEAKAGE TEST

Operator NORTHWEST PIPELINE CORPORATION Lease ROSA UNIT Well No. 112Y
Location
of Well: Unit M Sec. 27 Twp. 31N Rge. 5W County RIO ARRIBA Meter # 85941, 85940

	NAME OF RESERVOIR OR POOL	TYPE OF PROD (Flow or Art. Lift)	METHOD OF PROD. (Flow or Art. Lift)	PROD. MEDIUM (Tbg. or Csg.)
Upper Completion	UNDES. GALLUP	GAS	FLOWING	CASING
Lower Completion	BASIN DAKOTA	GAS	FLOWING	TUBING

PRE-FLOW SHUT-IN PRESSURE DATA

Upper Completion	Hour, date shut-in 8-18-94	Length of time shut-in 5 DAYS	SI press. psig SICP = 345	Stabilized? (Yes or No) NO
Lower Completion	Hour, date shut-in 8-18-94	Length of time shut-in 5 DAYS	SI press. psig SITP = 0	Stabilized? (Yes or No) NO

FLOW TEST NO. 1

Commenced at (hour, date)* 8-26-94				Zone producing (Upper or Lower) MV LOWER	
TIME (hour, date)	LAPSED TIME SINCE*	PRESSURE		PROD. ZONE TEMP.	REMARKS
		Upper Completion	Lower Completion		
8-26-94	24 HOURS	CSG	TBG		Q = 0 MCF/D
		346	0		
8-27-94	48 HOURS	348	0		Q = 0 MCF/D

REMARKS: TURNED ON UPPER ZONE FOR FLOW. LOGGED NO FLOW

I hereby certify that the information herein contained is true and complete to the best of my knowledge.

Approved AUG 19 1994 19____
New Mexico Oil Conservation Division
By *Charles E. Hester*
Title DEPUTY OIL & GAS INSPECTOR, DIST. #3

Operator NORTHWEST PIPELINE CORPORATION
By Sterg Katirgis
Title Senior Engineer
Date 9/15/94

RECEIVED
SEP 19 1994

OIL CON. DIV.
DIST. 3