

F

30-039-23945

11-27-85

F. Loc. 1080/N; 1505/E Elev. 6778 GL Spd. \_\_\_\_\_ Comp. \_\_\_\_\_ TD \_\_\_\_\_ PB \_\_\_\_\_  
 Cu. ft. \_\_\_\_\_ Cu. ft. \_\_\_\_\_ Cu. ft. \_\_\_\_\_  
 Casing S. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. Int. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. Pr. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. T. \_\_\_\_\_ @ \_\_\_\_\_  
 Csg. Perf. \_\_\_\_\_ Prod. Stim. \_\_\_\_\_

BO/D \_\_\_\_\_ Grav. \_\_\_\_\_ 1st Del. Gas  
 I.P. \_\_\_\_\_ MCF/D After \_\_\_\_\_ Hrs. SICP \_\_\_\_\_ PSI After \_\_\_\_\_ Days GOR \_\_\_\_\_ 1st Del. Oil

TOPS		NiTD X	Well Log	TEST DATA						
Ojo Alamo		C-103	Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.
Kirtland		C-104	Electric Log							
Fruitland			C-122							
Pictured Cliffs		Ditr	Dfa							
Chacra		Datr	Dac							
Cliff House										
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrado										
		Acres 160								

P

o

o Laguna-

I Seca Gal. Co. RA S 28 T 31N R 5W UB Oper. Amoco Production Co. Lse. Rosa Unit No. 123

Rosa Unit #123

B-28-31N-5W

AMOCO PRODUCTION CO.

F

30-039-23945

11-27-85

F. Loc. 1080/N; 1505/E Elev. 6778 GL Spd. Comp. TD PB  
 Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @ T Gas  
 Csg. Perf. Prod. Stim.

Grav. 1st Del. Gas

I.P. BO/D MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oil

TOPS		NITD X	Well Log	TEST DATA							Ref.No.
Ojo Alamo		C-103	Plat X	Schd.	PC	Q	PW	PD	D		
Kirtland		C-104	Electric Log								
Fruitland			C-122								
Pictured Cliffs		Ditr	Dfa								
Chacra		Datr	Dac								
Cliff House		Acres N/320									
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											

P  
o  
o  
o

Basin Dak. Co. RA S 28 T 31N R 5W UB Oper. Amoco Production Co. Lse. Rosa Unit

No. 123

JAN 12 1987

Amoco Production Company  
2325 E. 30th Street  
Farmington, NM 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) for the following wells:

1. No. 122 Rosa Unit, located in the SW/4SW/4 sec. 28, T. 31 N., R. 5 W., Rio Arriba County, New Mexico on lease SF-078769.
2. No. 123 Rosa Unit, located in the NW/4NE/4 sec. 28, T. 31 N., R. 5 W., Rio Arriba County, New Mexico on lease SF-078769.
3. No. 125 Rosa Unit, located in the NW/4NE/4 sec. 13, T. 31 N., R. 6 W., Rio Arriba County, New Mexico on lease SF-078767.
4. No. 126 Rosa Unit, located in the SW/4SW/4 sec. 14, T. 31 N., R. 6 W., Rio Arriba County, New Mexico on lease SF-078771.

The subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 15 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, will result in assessment of liquidated damages.

Sincerely,

/s/ John L. Keller

FOR: Ron Fellows  
Area Manager

4 Enclosures

cc:  
NMOCD (2)

RECEIVED  
JAN 15 1987  
OIL CON. DIV.  
DIST. 3

ABANDONED LOCATION