

F

30-039-23946

11-27-85

F. Loc. 1120/S; 1190/W Elev. 6508 GL Spd. \_\_\_\_\_ Comp. \_\_\_\_\_ TD \_\_\_\_\_ PB \_\_\_\_\_  
 Casing S. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. Int. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. Pr. \_\_\_\_\_ @ \_\_\_\_\_ W \_\_\_\_\_ Sx. T. \_\_\_\_\_ @ \_\_\_\_\_  
 Csg. Perf. \_\_\_\_\_ Prod. Stim. \_\_\_\_\_

T Gas  
R  
A  
N  
S

BO/D \_\_\_\_\_ Grav. \_\_\_\_\_ 1st Del. Gas \_\_\_\_\_  
 I.P. \_\_\_\_\_ MCF/D After \_\_\_\_\_ Hrs. SICP \_\_\_\_\_ PSI After \_\_\_\_\_ Days GOR \_\_\_\_\_ 1st Del. Oil \_\_\_\_\_

| TOPS            | NiTD X    | Well Log     | TEST DATA |    |   |    |    |   |          |
|-----------------|-----------|--------------|-----------|----|---|----|----|---|----------|
|                 |           | Plat X       | Schd.     | PC | Q | PW | PD | D | Ref. No. |
| Ojo Alamo       | C-103     | Electric Log |           |    |   |    |    |   |          |
| Kirtland        | C-104     |              |           |    |   |    |    |   |          |
| Fruitland       |           | C-122        |           |    |   |    |    |   |          |
| Pictured Cliffs | Ditr      | Dfa          |           |    |   |    |    |   |          |
| Chacra          | Datr      | Dac          |           |    |   |    |    |   |          |
| Cliff House     |           |              |           |    |   |    |    |   |          |
| Menefee         |           |              |           |    |   |    |    |   |          |
| Point Lookout   |           |              |           |    |   |    |    |   |          |
| Mancos          |           |              |           |    |   |    |    |   |          |
| Gallup          |           |              |           |    |   |    |    |   |          |
| Greenhorn       |           |              |           |    |   |    |    |   |          |
| Dakota          |           |              |           |    |   |    |    |   |          |
| Entrada         |           |              |           |    |   |    |    |   |          |
|                 | Acres 160 |              |           |    |   |    |    |   |          |

P  
o

o Laguna-

I Seca Gal. Co. RA S 28 T 31N R 5W UM Oper. Amoco Production Co. Lse. Rosa Unit No. 122

Rosa Unit #122

M-28-31N-5W

AMOCO PRODUCTION CO.

F

30-039-23946

11-27-85

F. Loc. 1120/S; 1190/W Elev. 6508 GL Spd. \_\_\_\_\_ Comp. \_\_\_\_\_ TD \_\_\_\_\_ PS \_\_\_\_\_  
 Cu. ft. \_\_\_\_\_ Cu. ft. \_\_\_\_\_  
 Coaling S. \_\_\_\_\_ W \_\_\_\_\_ S. Int. \_\_\_\_\_ W \_\_\_\_\_ S. Pr. \_\_\_\_\_ W \_\_\_\_\_ S. T. \_\_\_\_\_  
 Csg. Perf. \_\_\_\_\_ Prod. Stm. \_\_\_\_\_

T Gas  
R  
A  
N  
SGrav. \_\_\_\_\_ 1st Del. Gas

I.P. \_\_\_\_\_ BO/D \_\_\_\_\_ MCF/D After \_\_\_\_\_ Hrs. SICP \_\_\_\_\_ PSI After \_\_\_\_\_ Days GOR \_\_\_\_\_ 1st Del. Oil

| TOPS            |  | N/TD X           | Well Log     | TEST DATA |    |   |    |    |   |         |
|-----------------|--|------------------|--------------|-----------|----|---|----|----|---|---------|
|                 |  |                  |              | Sched.    | PC | Q | PW | PD | D | Ref.No. |
| Ojo Alamo       |  | C-103            | Plot X       |           |    |   |    |    |   |         |
| Kirtland        |  | C-104            | Electric Log |           |    |   |    |    |   |         |
| Fruitland       |  |                  | C-122        |           |    |   |    |    |   |         |
| Pictured Cliffs |  | Dtr              | Dia          |           |    |   |    |    |   |         |
| Chacra          |  | Datr             | Dec          |           |    |   |    |    |   |         |
| Chin House      |  | Abandon location |              |           |    |   |    |    |   |         |
| Monette         |  |                  |              |           |    |   |    |    |   |         |
| Point Lookout   |  |                  |              |           |    |   |    |    |   |         |
| Mencos          |  |                  |              |           |    |   |    |    |   |         |
| Gallup          |  |                  |              |           |    |   |    |    |   |         |
| Greenhorn       |  |                  |              |           |    |   |    |    |   |         |
| Dakota          |  |                  |              |           |    |   |    |    |   |         |
| Entrada         |  |                  |              |           |    |   |    |    |   |         |
|                 |  | Acres S/320      |              |           |    |   |    |    |   |         |

9  
•  
•  
•

Basin Dak. Co. RA S 28 T 31N R 5W UM Oper. Amoco Production Co. Loc. Rosa Unit No. 122

JAN 12 1987

Amoco Production Company  
2325 E. 30th Street  
Farmington, NM 87401

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) for the following wells:

1. No. 122 Rosa Unit, located in the SW/4SW/4 sec. 28, T. 31 N., R. 5 W., Rio Arriba County, New Mexico on lease SF-078769.
2. No. 123 Rosa Unit, located in the NW/4NE/4 sec. 28, T. 31 N., R. 5 W., Rio Arriba County, New Mexico on lease SF-078769.
3. No. 125 Rosa Unit, located in the NW/4NE/4 sec. 13, T. 31 N., R. 6 W., Rio Arriba County, New Mexico on lease SF-078767.
4. No. 126 Rosa Unit, located in the SW/4SW/4 sec. 14, T. 31 N., R. 6 W., Rio Arriba County, New Mexico on lease SF-078771.

The subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 15 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, will result in assessment of liquidated damages.

Sincerely,

John L. Kasper

FOR  
Ron Fellows  
Area Manager

4 Enclosures

cc:  
NMOCD (2)

RECEIVED  
JAN 12 1987  
DIV.

ABANDONED LOCATION